

(08/11/13) wef

ASS. REC. BY: Resul

REF:

CS3/11121007046/R19f3

341B

COC XP124: 2023/SEP

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJJ 1376Mat Workshop m/s A TEL MOTORS P/Lof 39, WOODLAND CLOSE #02-43 (MEHA)

Insured:

111

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

17k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJJ 1376MYr Regn: 2008 / SEPType: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA COROLLA MATIS 1.6A c.c 1598

Colour:

GREY

A/C: Insured / Std / NI / NA

Sp. Reading

351090

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MROS3 ZEE106115131Gen. Cond: Good / Poor / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEKEN

Front

Rear

R/Bal.

S

mm

R/Bal.

5

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

22/06/21

D.O.I.

28/06/21

Survey held at

A-TEL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S PR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 10KESTIMATE RANGE OF REPAIR / NO. OF DAYS - (OK-3K) / 4 days

14/07/21 Submit PRS.

Date/Time, File Pass to?

☐

: Prel. Report

1) 14/07 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS SI☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

Report Format:

MER-PRS

Lump Sum / I B I / S

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	341B
Vehicle No.:	SJJ1376M
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jun 2021
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4786262
Chassis No.:	MR053ZEE106115131
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,777.00
Original Registration Date:	02 Sep 2008
First Registration Date:	02 Sep 2008
Transfer Count:	1
Actual ARF Paid:	\$13,066.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	01 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,170.00
COE Rebate Amount:	\$7,033.00
Total Rebate Amount:	\$7,033.00
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Jun 2021

OK

Toyota Corolla Altis 1.6A (COE till 09/2023)

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$17,800		
Depreciation ?	\$7,940 /yr	Reg Date	26-Sep-2008 (2yrs 2mths 27days COE left)
Mileage	96,000 km (7.5k /yr)	Manufactured ?	2008
Road Tax ?	\$965 /yr	Transmission	Auto
Dereg Value ?	\$7,248 as of today (change)	OMV ?	\$16,777
COE ?	\$16,170	ARF ?	\$16,777
Engine Cap	1,598 cc	Power	80.0 kW (107 bhp)
Curb Weight ?	1,195 kg	No. of Owners ?	5