



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21007049/Aqf3n2 Date: 23/07/2021	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGC 8888D	Veh. Inspected	SJN 727U	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10010648/CD	Excess (\$)	0.00	
Assign From	STANLEY LAI	Assign Date	25/06/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA RUSH	c.c	1495	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	J200E0020610	Colour	BLACK	
Odometer	138024 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	FALKEN	6 mm	
L/H Front Tyre	215/60 R16	FALKEN	6 mm	
R/H Rear Tyre	215/60 R16	FALKEN	6 mm	
L/H Rear Tyre	215/60 R16	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/06/2021	Inspection Date	28/06/2021	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	