

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SMRT AUTOMOTI	VE SERVICES PTE LTD		Ref:	CS/SMR21007074/Uuf3e2	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 37705		Date:	21/07/2021	
				Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHC 4605T	Veh. Inspected	l	SJQ 7811Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/06/21/2056	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		28/06/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI LANCER (A)	c.c		1499	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	JMYSRCY2A9U004210	Colour		WHITE	
	Odometer	141694 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	HABILEAD		6 mm	
	L/H Front Tyre	205/60 R16	HABILEAD		6 mm	
	R/H Rear Tyre	205/60 R16	HABILEAD		6 mm	
	L/H Rear Tyre	205/60 R16	HABILEAD		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	26/06/2021	Inspection Dat	е	28/06/2021	
	Survey held at	TAN LIM MOTOR PTE LTD	•			
		NO.1 DEFU LANE 6 SINGAPORE 539365				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:		14 Wor	king Days	
SD.	ESTIMATED NORMAL PERIOD FOR REPAIR: 14 Working Days					