

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SMRT AUTOMOTI	VE SERVICES PTE LTD	Re	f: CS/SMR21007091/Buf3e2	
	60 WOODLANDS E4SINGAPORE 75	NDUSTRIAL PARK 37705	Da	te: 21/07/2021	
			Co	de: SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6219G	Veh. Inspected	SJS 7947D	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	TAX/06/21/2048	Excess (\$)	0.00	
	Assign From	HUA YEN	Assign Date	28/06/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN SCIROCCO 1.4L TSI	c.c	1390	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	WVWZZZ13ZAV406633	Colour	WHITE	
	Odometer	178556 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	235/40 R18	FALKEN	5 mm	
	L/H Front Tyre	235/40 R18	FALKEN	5 mm	
	R/H Rear Tyre	235/40 R18	AZENIS	5 mm	
	L/H Rear Tyre	235/40 R18	AZENIS	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	23/06/2021	Inspection Date	29/06/2021	
	Survey held at ACCIDENT ASSIST SG				
	24 SIN MING LANE, #01-94, MIDVIEW CITY, SINGAPORE 573970				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days				
	<u> </u>				