

(08/11/13) wef

ASS. REC. BY: Paul

REF:

CS/AH121007095/R19/3

4672

COE EXPIRY: 2024/AH

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFM 75754at Workshop m/s AP AUTOMOTIVEof 56, Loyamh way #04-04

Insured:

AH1

Policy No.

Claims No. C10010665/JM


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

95K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFM 75754Yr Regn: 2014 / AHType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W 328I GT 5025R c.c 1997

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp.Reading

171768

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA3X32080D444577Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

24/06/21

D.O.I.

29/06/21

Survey held at

AP AUTOMOTIVE

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

REAR N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 36K

Rasul finalised LS \$4250, 4 days. (Red \$18463.06, 81%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 12/05 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS \$☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format: TPLump Sum / L.B.H. (\$ 4250)

AP Automotive Services

AP AUTOMOTIVE SERVICES PTE LTD
ROC: 202022890H
BLOCK 9006
TAMPINES STREET 93 #01-202
SINGAPORE 528840
TEL: 6784 4465
FAX: 6787 4886

Estimation

Date
Vehicle
Make/Model
Chassis No.

SFN 7575 Y
BMW 328i GT
WBA3X32080D444577

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BOOTLID <i>lt</i>	1	\$	-
2	BOOTLID LOGO - BMW <i>ne</i>	1	\$	-
3	BOOTLID EMBLEM - GT <i>ne</i>	1	\$	-
4	BOOTLID EMBLEM - 328i <i>ne</i>	1	\$	-
5	BOOTLID LAMP L+R <i>x</i>	1	\$	-
6	BOOTLID LOCK <i>x</i>	1	\$	-
7	BOOTLID LOCK CATCH <i>x</i>	1	\$	-
8	BOOTLID INNER TRIM <i>x</i>	1	\$	-
9	BOOTLID HINGE L+R <i>x</i>	2	\$	-
10	BOOTLID WEATHERSTRIP <i>ne</i>	1	\$	-
11	TAIL LAMP L+R <i>x</i>	2	\$	-
12	TAIL LAMP INNER GARNISH L+R <i>x</i>	2	\$	-
13	TAIL LAMP LOWER BRACKET L+R <i>x</i>	2	\$	-
14	REAR BUMPER <i>de</i>	1	\$	-
15	REAR BUMPER CENTER CHROME <i>ca</i>	1	\$	-
16	REAR BUMPER REVERSE SENSOR <i>?</i>	4	\$	-
17	REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>x</i>	1	\$	-
18	REAR BUMPER TOW COVER <i>x</i>	1	\$	-
19	REAR BUMPER REFLECTOR L+R <i>x</i>	2	\$	-
20	REAR BUMPER RETAINER L+R <i>x</i>	2	\$	-
21	REAR BUMPER REINFORCEMENT BAR <i>?</i>	1	\$	-
22	REAR BUMPER CENTER BRACKET <i>?</i>	1	\$	-
23	REAR BUMPER SPONGE <i>?</i>	1	\$	-
24	REAR BUMPER UNDERCOVER <i>x</i>	1	\$	-
25	REAR FENDER INNER TRIM RH <i>x</i>	1	\$	-
26	REAR FENDER COWLING RH <i>x</i>	2	\$	-
27	END PANEL <i>x</i>	1	\$	-
28	END PANEL TOP GARNISH <i>x</i>	1	\$	-
29	REAR SMART LOCK ANTENNA <i>x</i>	1	\$	-
30	REAR BOOT KICK SENSOR <i>x</i>	1	\$	-
31	SPAREWHEEL PANEL <i>x</i>	1	\$	-
32	SPAREWHEEL PANEL TOP BOARD <i>x</i>	1	\$	-
33	EXHAUST PIPE <i>?</i>	1	\$	-
34	EXHAUST HEAT SHEILD <i>x</i>	1	\$	-
			Total	\$ -
			Less 5%	\$ -
			Total	\$ -

S/Nett Items					
1	BOOTLID INNER TRIM CLIP SET <i>new</i>	1	100	\$	40.00 100.00
2	REVERSE CAMERA <i>X</i>	1	850	\$	850.00
3	REAR NUMBER PLATE <i>X</i>	1	120	\$	120.00
4	TAIL LAMP CLIP <i>X</i>	1	50	\$	50.00
5	TAIL LAMP PANEL SEALANT <i>X</i>	2	150	\$	300.00
6	REAR BUMPER CLIP <i>new</i>	1	100	\$	40.00 100.00
7	REAR FENDER INNER TRIM CLIP <i>X</i>	1	200	\$	200.00
8	REAR FENDER COWLING CLIP <i>X</i>	1	200	\$	200.00
9	END PANEL SEALANT <i>X</i>	1	250	\$	250.00
10	END PANEL TOP GARNISH CLIP SET <i>X</i>	1	100	\$	100.00
Total				\$	2,270.00

LABOUR					
1	PANEL BEATING ON AFFECTED AREAS	1	2200	\$	400.00 2200.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1750	\$	500.00 1750.00
3	TO RNR REAR WINDSCREEN	1	400	\$	X 400.00
4	TO RNR REAR EXHAUST <i>photo?</i>	1	300	\$? 80.00 300.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION	1	150	\$	X 150.00
6	TO CHECK WIRING AND BOOTLID LAMP FUNCTION	1	150	\$	X 150.00
7	TO RNR REAR INNER TRIM AND UPHOLSTERY	1	600	\$	X 600.00
8	TO CHECK WHEEL ALIGNMENT AND ADJUST	1	250	\$	X 250.00
9	TO RNR UNDERCARRIAGE	1	250	\$	X 250.00
10	TO CHECK WHEEL BALANCING	1	250	\$	X 250.00
11	TO CHECK WATER LEAK	1	150	\$	X 150.00
12	TO RNR FUEL TANK	1	250	\$	X 250.00
13	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	1200	\$	X 1,200.00
14	TO RNR REAR BOOTLID MECHANISM	1	400	\$	60.00 400.00
15	TO RNR REAR BOOT KICK SENSOR	1	300	\$	X 300.00
16	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$	60.00 150.00
17	TO PERFORM RUST PROOFING	1	400	\$	40.00 400.00
Total Labour				\$	9,150.00
Parts Replacement Amount				\$	2,270.00
Total Amount				\$	11,420.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068
4 days
L/s
29/06/21 @ 1730
Resy after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/06/2021 16:19 (SGT)
Date of Accident	24/06/2021 14:50 (SGT)
Exact Location of Accident	Yishun Ave 1, Singapore
Additional Location Information	BEFORE LENTOR AVENUE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFM7575Y
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	PAYRICK TAN KIM YEW
NRIC No	SXXXX467I
Email Address	diionaw@gmail.com
Mobile Phone No	(Phone) +65-82000939
Alternative Phone No	+65-82685050

VEHICLE PARTICULARS

Manufacturer	BMW
Model	328i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1997

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1700067826-03
Cover Note Number	-

DRIVER

Name of Driver	POH WEE LING, PRISSY
NRIC No	SXXXX062G

Date Of Birth	20/11/1992
Occupation	Outdoor
Date Of Driving Pass	01/09/2012
Driving experience	8 YEARS AND 9 MONTHS
Gender	Female
Mobile Number	(Phone) +65-82685050
Alt. Phone Number	-
Email Address	diionaw@gmail.com
Address	12 JALAN KECHUBONG
Address complement	-
Postcode	799371
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	WITH OWNER
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ9412C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-

Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

Ins
t W
of
Ins
P

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

YISHUN AVE 1 BAYFORK LANE ARUMUK



A : SFM7575Y
B : SJQ9412C

Describe Circumstances of the Accident

I, Vehicle A, was travelling straight in my lane.
The vehicle in front brake so I also brake.
Suddenly, Vehicle B, Bang onto me the rear portion
of my vehicle.


I did not dare to alight because it was my first time.
accident and the other party also wasn't wearing
any mask in his vehicle.


So I drove to the nearest car park to check on my
car and realised there was dents and damages on
my vehicle.

I like to state that, After I checked on my
car, I also receive notification in my car that
my rear spoiler was ~~not~~ malfunction.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time


Driver's Signature (If driver is not the policyholder) / Date
& Time

 26/06/2021
Witnessed by Reporting Centre
Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	467I

Vehicle Details

Vehicle No.:	SFM7575Y
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jul 2021
Vehicle Make:	B.M.W.
Vehicle Model:	328I GT 5DR SR HUD HID DSC NAV
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	B0640861N20B20A
Chassis No.:	WBA3X32080D444577
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$51,049.00
Original Registration Date:	21 Aug 2014
First Registration Date:	21 Aug 2014
Transfer Count:	2
Actual ARF Paid:	\$58,889.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Aug 2024
PARF Rebate Amount:	\$38,277.00

Intended COE Rebate Details

COE Expiry Date:	20 Aug 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$65,002.00
COE Rebate Amount:	\$19,849.00
Total Rebate Amount:	\$58,126.00

The information contained herein is correct as at 25 Jun 2021

OK

BMW 3 Series 328i Gran Turismo

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$80,888****Depreciation** ?

\$21,180 /yr

[View models with similar depre](#)**Reg Date**

18-Dec-2013

(2yrs 5mths 18days COE left)

Mileage

85,000 km (11.3k /yr)

Manufactured ?

2013

Road Tax ?

\$1,210 /yr

Transmission

Auto

Dereg Value ?\$53,895 as of today ([change](#))**OMV** ?

\$50,111

COE ?

\$79,300

ARF ?

\$57,200

Engine Cap

1,997 cc

Power

180.0 kW (241 bhp)

Curb Weight ?

1,595 kg

No. of Owners ?

2

Type of Vehicle

Luxury Sedan

Features

BMW 2.0L Twin Turbo Engine Producing 241bhp, 8 Speed Transmission, Keyless Entry/Start Function, Paddle Shifters, 0 To 100Km/H In Just 6.1s. View specs of the [BMW 328i](#)