

ASS. REC. BY: Tan JH

REF:

CS/C T121007096/TVC

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 984K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WPI

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SFV80404 Yr Regn: 2019, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Monte Carlo c.c. 1496

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 25753 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 24/1321510

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 29/6/21 @ 12pm

Survey held at 7-Due

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: \_\_\_\_\_

Lump Sum / L&A: \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Photos

Others

TOTAL



# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: [service@z-one.com.sg](mailto:service@z-one.com.sg); [enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

## ESTIMATE

Kway Too Hwee  
541 Hougang Ave 8, #03-1215 Singapore 530541  
Contact : 98369385 66342112

Code : C102001  
Date in : 28/06/2021  
Vehicle Num. : SFV8040U  
Model : HONDA VEZEL 1.5X CVT  
Chassis/Eng# : RU11321310/L15B5571348

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
LH side skirt assy	1	334.10 <i>nn x</i>	334.10
Rear bumper	1	1161.50 <i>cut</i>	1,161.50
Rear bumper reflectors LH	1	181.00 <i>nn x</i>	181.00
Rear bumper side garnish LH	1	259.20 <i>de</i>	259.20
Rear bumper side retainers LH	1	44.00 <i>na</i>	44.00
Rear bumper side spacer LH	1	27.00 <i>na</i>	27.00
Rear fender inner cowling LH	1	157.50 <i>de</i>	157.50
Rear fender inner garnishes LH	1	240.90 <i>nn x</i>	240.90
Rear fender LH	1	982.80 <i>Rx</i>	982.80
Rear LH door panel	1	1262.40 <i>Rx</i>	1,262.40
Rear wheel arch garnish assy LH	1	280.80 <i>de</i>	280.80
Subtotal before discount		1930	4,931.20
Percentage discount 20%		1544	986.24
Sub-total 1			3,944.96
Rear Bumper Clips (Set) (SN)	1	50.00 <i>30</i>	50.00
Rear Fender Inner Clips (SET) (SN)	1	50.00 <i>20</i>	50.00
Subtotal before discount			100.00
Percentage discount 0%		50	0.00
Sub-total 2			100.00
Parts-total			4,044.96



# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: [service@z-one.com.sg](mailto:service@z-one.com.sg); [enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

## LABOUR

Description	Price
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.	30. 150.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	600 1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	600 1,000.00
<b>Labour Total</b>	<b>1230 2,150.00</b>
<b>Parts &amp; Labour Total</b>	<b>6,194.96</b>

page 2

1544  
 50  
 1230  
 'up' 29/6/21 @ 11/15 2824  
 4/5 Resurvey after repair 4/5 @ 2250  
 tariff @ 11/15 @ 2250 4 days  
 4-5 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SS1Y2160000B / SME MOTOR PTE LTD  
ENTRY DATE & TIME: 24/06/2021 15:58 (SGT)  
SUBMITTED BY: Chia Pei Ying  
VERSION: 1 (24/06/2021 15:58 (SGT))



## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission 24/06/2021 15:58 (SGT)  
Date of Accident 23/06/2021 22:10 (SGT)  
Exact Location of Accident 538 Hougang Street 52, Block 538, Singapore 530538  
Additional Location Information -  
Country/State of Loss Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SFV8040U  
INSURED/POLICYHOLDER  
Is company? No  
Name Of Registered Owner KWAY TOO HWEE  
NRIC No SXXXX633E  
Email Address michael.kway64@gmail.com  
Mobile Phone No (Phone) +65-98369385  
Alternative Phone No (Office) +65-66342112

## VEHICLE PARTICULARS

Manufacturer Honda  
Model Vezel  
Variant -  
Exact purpose for which vehicle was being used at time of accident Private use  
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party  
Vehicle Category Private car  
Transmission Auto  
CC 1496

## INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd  
Type of Coverage Comprehensive  
Fleet Policy No  
Policy Number 5119644786  
Cover Note Number -

## DRIVER

Name of Driver KWAY TOO HWEE  
NRIC No SXXXX633E

Date Of Birth	07/09/1964
Occupation	Indoor
Date Of Driving Pass	24/08/1982
Driving experience	38 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98369385
Alt. Phone Number	(Office) +65-66342112
Email Address	michael.kway64@gmail.com
Address	BLK 541 HOUGANG AVE 8 #03-1215
Address complement	-
Postcode	530541
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

## GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

## OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

## DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

## CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT: T/20210624/7004.

## ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

## DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE6181X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE B
No. Of Passenger (Including Driver)	-

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGS7676X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE C
No. Of Passenger (Including Driver)	-






SKETCH PLAN #2

SKETCH PLAN

BIK 532 HONGANG

CAYPERA



Vehicle A - SPYGLASS  
Vehicle B - GREENIX  
Vehicle C - SCSHUX

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to  
Police report

DECLARATION

I hereby declare that the information provided in this report is true and correct.

Signature of Driver

Signature of Driver

Signature of Driver



POLICE REPORT



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20210624/7034

1 of 3

Report No T/20210624/7034

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/06/2021 10:54		Vide Report No.: F/20210623/0203	Station Diary No.:
<b>Informant's Particulars</b>			
Name of Informant: KWAY TCO HWEE		Address: 541 HOUGANG AVENUE 8 #03-1215 SINGAPORE 530541	
ID Type / ID No.: NRIC NO / S1633633E		Contact No.: Home/Office: Mobile: 98369385	
Nationality: SINGAPORE CITIZEN		Email: michael.kway64@gmail.com	
Sex: Male	Age: 56	Date of Birth: 07/09/1964	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Motor vehicle mechanic		Driving Licence Information: Class: Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident: Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/06/2021 22:10	Type of Location: Car Park	
Location: 538 HOUGANG STREET 52				
Weather: Clear		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of
GBE6181X	Lorry	TOYOTA	DYNA			2
SFV8040U	Car	HONDA	VEZEL 1.5X CVT	Red	Seriously Damaged	0
SGS7676X	Car	HONDA			Seriously Damaged	0

POLICE REPORT #2



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408665  
Tel No: 65470000



T:20210624/7004

2 of 3

Report No. T:20210624/7004

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SFV8040U	NTUC Income Insurance Co-Operative Limited	5119644786	27/11/2020	26/11/2021

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL				
Use of Pedestrian Crossing: NA				
Driver				
Name	KWAY TOO HWEE		ID No.	S1633633E
Related Vehicle	SFV8040U (Car)		Contact No.	98369385
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	NIL

## Brief Details.

On 23.06.2021 at about 1010pm, I was at the carpark of 538 Hougang Street 52. As I entered the carpark, I saw the lorry GBE6181X Toyota Dyna, reversing and hit onto another vehicle- SGS7676X Honda & damaging it.

I wind down my window and tried to tell the driver of GBE6181X that he had hit onto the vehicle- SGS7676X.

However, the passenger of GBE6181X told the driver to just drive off. While doing so, vehicle- GBE6181X hit onto the rear portion of my vehicle.

The vehicle- GBE6181X had 2 passengers & 1 driver in the lorry.

The vehicle- SGS7676X was parked stationary & no one was in the vehicle.

I tried to stop the vehicle by chasing it, but they drove too fast and I was unable to catch up.

I came back to the carpark and called 911 for assistance. They send down the Traffic Police Sgt Shahzan to come and make the report.

The police managed to get hold of the owner of SGS7676X and I told them what had happened.

I have a video footage of the incident and captured the photo of the vehicle GBE6181X.

I'll be making an accident report to my insurance for insurance claim purposes.

POLICE REPORT #3



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20210624/7004

3 of 3

Report No. T/20210624/7004

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPHQ /  
LIM ENG KUAN, CLARENCE  
Contact No.: 65476200

Authentication Stamp  
NP165

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by Singpass. No signature is  
required.

Date/Time:  
24/06/2021 10:54

Classification Of Case: