

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21007099/Avf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	23/07/2021	
			Code	: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMA 4490H	Veh. Inspected	SLF 3378S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10010687/JM	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	28/06/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3	C.C	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JM6BM42A8G0339820	Colour	WHITE	
	Odometer	76528 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
	L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
	R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
	L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	26/06/2021	Inspection Date	29/06/2021	
	Survey held at	MG SOLUTION PTE LTD			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

**6 Working Days** 

ESTIMATED NORMAL PERIOD FOR REPAIR: