ASSIGNMENT

From: Date:	Veh No: SLK 6699U. Yr Regn: 2021/Jan.
Estimated Cost:	Type M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Meredos Berz GLB200 c.c 1332
at Workshop m/s	Colour Grey . A/C: Insured / Std / NI / NA
of	Sp.Reading 7958 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WIN24768724049984
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Morder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi : Nil /S/Rim / STD A/Rim or
	Tyre Size: F: 235/55R18
(Policy Condition)	R: 235/55R18
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIRY SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 06 mm L/Bal. 96 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 29/00/21,
Lum Sum: % 3 Val.: Yes or No	Survey held at SK
CA I DEV I DED I 24 HDS	Des. of Damages : Frt / Rean / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	THE REPORT OF THE PARTY OF THE
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	,
TP Brigget Direct.	140
MV:	
PV:	
Nett;	
	•
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
; Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee	: Site Insp (\$)_3+RS_SI
No. 2 Are the We Street S.	: Interview (\$) Photos
Report Format :	: Tech. Invs (3) Others
Lump Sum / LB.E (\$: Weel end (\$)
Commence Statement of American American American	. 707.8L

SA1E216P0006 / Abwin Service Pte Ltd ENTRY DATE & TIME: 25/06/2021 17:30 (SGT) SUBMITTED BY: Gerine Cheng VERSION: 1 (25/06/2021 17:30 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process
- This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 25/06/2021 17:30 (SGT) Date of Accident 24/06/2021 08:20 (SGT) **Exact Location of Accident** KPE, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Mercedes

1332

Vehicle Registration Number SLK6699U

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner LIM KUAN NGEE NRIC No SXXXX886A Email Address mike@onecopier.com.sg Mobile Phone No (Phone) +65-90889025 Alternative Phone No (Home) +65-90889025

VEHICLE PARTICULARS

Manufacturer

Model **GLB200** Variant Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto

INSURANCE COMPANY

Liberty Insurance Pte Ltd Name of Insurance Company Type of Coverage Comprehensive Fleet Policy No Policy Number SI21V01425/VPE/R00 Cover Note Number

DRIVER

CC

Name of Driver LIM KUAN NGEE NRIC No SXXXX886A

Date Of Birth 22/03/1967 Occupation Indoor Date Of Driving Pass 28/11/1996 Driving experience 24 YEARS AND 7 MONTHS Gender Male Mobile Number (Phone) +65-90889025 Alt. Phone Number (Home) +65-90889025 Email Address mike@onecopier.com.sg Address 316C PUNGGOL WAY Address complement #06-699 Postcode 823316 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 4 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? Yes Police Station Name Traffic Police Police Station Phone No. (Phone) +65-65470000 Alt. Police Station Phone No (Fax) +65-65474900 Police Station Address 10 Ubi Avenue 3 Singapore 408865 Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN & POLICE REPORT ATTACHED. ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? No Was there any audio recorded? **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SMV7924T Vehicle Manufacturer Vehicle Model Vehicle Variant

Private car

Vehicle Colour Vehicle Category

Name of Driver	-
Contact Number	_
Address	_
Address complement	-
Postcode	-
Insurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLQ2796S
Vehicle Manufacturer	01427300
Vehicle Model	
Vehicle Variant	-
Vehicle Colour	-
	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	
Address	-
Address complement	-
Postcode	4
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SLE7555B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	_
Postcode	
Insurance Company Name	_
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	LIM KUAN NGEE
Address	316C PUNGGOL WAY
Address Complement	#06-699
Post Code	823316
Approximate Age Years Old	
Injuries Sustained	2 DAYS OF MEDICAL LEAVE
Injured person in which vehicle?	SLK6699U
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Flease report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful insrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
 of Singapore (CIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of .
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collectuse, disclose and/or process my Personal information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

		A: SLK 6699U
K3E	I I I A	B: SMV 79247
TOWARDS ECP		C: SLQ 2796S D: SLE 7555B

REF_TO POLICE REPOR	7 7/20210,624/7.049	
· K		
A 1- A 1-	y	
		-
	1.	2
. , , , ,	0	
	. 0	
c-lik-		. 13
	,	-
-^-		
and to have their the		

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 1 of 3 Report No. T/20210624/7040

REPORT OF A TRAFFIC ACCIDENT

	Date/Time Report Made: 24/06/2021 22:23		Vide Report No.:	Station Diary No.:	
Informa	nt's Partic	ulars			
Name of Informant: LIM KUAN NGEE			Address: 316C PUNGGOL WAY #06-699 SINGAPORE 823316		
ID Type / ID No.: NRIC NO / S2584886A		86A	Contact No.: Home/Office: Mobile: 90889025		
National SINGAP	ity: ORE CITIZ	EN.	Email: mike@onecopier.com.sg		
Sex: Male	Age: 54	Date of Birth: 22/03/1967	Type of Informant:		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: Managing director/Chief executive officer		Chief executive	Driving Licence Information: Class: Date of Expiry:		

General Infor	mation of the Accident			
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/06/2021 08:20	Type of Location Straight Road
Location: KALLANG PA	YA LEBAR EXPRESSW	AY Road Surface:		Road Speed Limit:
Clear		Dry		
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collis Chain collision				Anyone conveyed by ambulance: Yes

Vehicle No.	Туре	Make	Model	Color	Conditio	No of
SLE7555B	Car					0
SLK6699U	Car					0
SLQ2796S	Car					1
SMV7924T	Car					1



Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000



3 of 3 Report No. T/20210624/7040

CONTINUATION OF REPORT

Cleatob	Dian
Sketch	ridii

Informant is not able to provide sketch

Signature Of Officer Recording The Report: The identity of the person making this report has Not applicable been authenticated by Singpass. No signature is required. Date/Time: Signature Of Interpreter: 24/06/2021 22:23 Not applicable Classification Of Case: Officer In Charge Of Case:

Signature Of Informant:

Authentication Stamp NP168

RASHIDAH BINTE AZMAN Contact No.: 65476216

TP/TPHQ/



T/20210624/7040

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 3 Report No. T/20210624/7040

CONTINUATION OF REPORT

Details of Perso	in Involved				
Any Pedestrian I	nvolved: No				
No. of Pedestrian	ns Injured: NIL		Use of Ped	destrian Cros	ssing: NA
Driver					
Name	LIM KUAN NGEE			ID No.	S2584886A
Related Vehicle	SLK6699U (Car)		Contact No	. 90889025	
Hospital/Clinic	NIL			Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	24/06/2021		Date	24/0	6/2021
No. of Days gran	ted Medical Leave	02	Degree of	Slig	nt

Brief Details.

On the above mentioned date and time, I was travelling along KPE towards ECP on lane 1 of 4 lanes. Weather was clear, traffic was moderate. The vehicle in front of me slowed down and stopped. Noticing that, I also slowed down and came to a halt. After a few second, I felt a great impact from the rear. I alighted and realised it was a chain collision involving 4 vehicles. I was the first vehicle from the front.

1st SLK6699U 2nd SMV7924T 3rd SLQ2796S 4th SLE7555B