

MOTOR SURVEY ASSIGNMENT

Date	25-06-2021	Our Ref No. D21001893MFCV
Accident Date	23-06-2021	Claim Type. Third Party
Insured Vehicle	XD4035T	Third Party Vehicle. GBD3932X
Survey Location	48 Toh Guan Rd East Enterprise Hub01-119, Gold Auto Works	
Contact Person.	WINSTON	
Contact No.	62640995/ 96199144	Fax No. 62645948
Survey Type	WITHOUT PREJUDICE: VERIFY TPV DAMAGE CONSISTENCY	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	GOLD AUTO WORKS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SANGHILAN VIC ALPEH SUMAGANG	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.