



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21007126/Uvf3n2 Date: 03/08/2021  Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMF 4640R	Veh. Inspected	SMA 8148X	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10010663/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	29/06/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	PORSCHE MACAN S (A)	c.c	2997	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WP1ZZZ95ZFLB60694	Colour	BLACK / BLUE	
Odometer	136020 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	265/45 R20	PIRELLI	7 mm	
L/H Front Tyre	265/45 R20	PIRELLI	7 mm	
R/H Rear Tyre	295/40 R20	MICHELIN	7 mm	
L/H Rear Tyre	295/40 R20	MICHELIN	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/06/2021	Inspection Date	29/06/2021	
Survey held at	BLK 15 KAKI BUKIT RD 4, BARTLEY BIZ CENTRE			
Repairer	ZOOM AUTOWERKS PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	