NATIONAL, Assessment Centre Date In: 28/6/2021 13:50	The state of the s			
0 0 20-1 .3.90	Jeb description	Date & Time Completed	Done l	p.i
Ref No NA) CTI 21007131/4	SAS e-filing	1		
Veh No: SMX 6216A	E-mail (widen Shrs. AIC 2	hrsj		
D.O.A. 25 6 2021 12:50	i-Motor Claim Form	1		
	i-Motor W/O (Within: C	OD 2hrs. TP 4hrs)		
OD TP / Reporting Only	i-Photo Uploaded		**************************************	
	Assessment/Survey Rep	oort ;		
TP Insurer:	Ass't Report by Fax / H	and to Owner/Wksp	and the second of the second o	2 2 2 30
Preferred Wksp / INC Assign Wksp / QW: (Tel: F	ax:	
TP Particulars: Veh No: SC3	79K II	NC()/Non-INC()		
Owner / Driver: (Tel:)	
Policy No: () Perio	od: () Cover Type: ()	- 1 1/4
Confirmed by : (Date:	Time:)	
Insured/Driver Liability: (%) [No	ote-Est. Status (WO): N	: 0-20%; P: 21-79%. F: 80-1	00%]	
Year of Registration: () W	arranty: YES ()/NO	()		
Excess: (\$) Loading: \$1,000	0 () / \$2,000 ()			
General Remarks:-				
() Walk-In Customer: Customer's inform	nation strictly Confidentia	& Strictly NO rafer of repairer.		
() Total Loss Case : to e-mail Insurer				and the second second second
); Towing Co. ()
Drive-In () / Towed-In (); Invoice:	TES()/ NO(
Remarks:- (INC horline: 6788 6616)		Date&Time Completed	Done	by
1) Apply for Transport Allowance () / Co	urtesy Car ()			
2) QC Check / Post Repair Inspection	()		a manage of the same of the sa	
2) QC Check / Post Repair Inspection3) Upload Resurvey Photo [Repair Cost > \$30	()			
3) Upload Resurvey Photo [Repair Cost > \$30	()	7,		- 73 (000)
3) Upload Resurvey Photo [Repair Cost > \$30 Injury:	()			
3) Upload Resurvey Photo [Repair Cost > \$30 Injury:	()			
3) Upload Resurvey Photo [Repair Cost > \$30 Injury:	()			
3) Upload Resurvey Photo [Repair Cost > \$30 Injury:	()			
3) Upload Resurvey Photo [Repair Cost > \$30 Injury:	()			
3) Upload Resurvey Photo [Repair Cost > \$30 Injury:	()			
3) Upload Resurvey Photo [Repair Cost > \$30 Injury:			Amt (\$)	Amt (\$)
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions		e Preparation Checklist	Amt (\$) 1st Bill	
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions NA 2103213	Invoice 1) AR:	Accident Reporting (\$30);	1st Bill	
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions NA 2103213 Claimant's Particulars:-	Invoic 1) AR : A 2) DA : 1	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$	1st Bill	
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions NA 2103213 Claimant's Particulars:-	Invoice 1) AR: A 2) DA: I 3) TF: T 4) FT: F	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$00) Fee \$000 October 100 October	1st Bill 580) 40/\$45 \$120	
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions NA 2103213 Claimant's Particulars:- Driver/Owner:	Invoice 1) AR: A 2) DA: I 3) TF: T 4) FT: F 5) FT: F	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$100); INC (\$100); INC (\$100); Owing Fee \$100] Ollow-Through Survey Ollow-Through Survey (Resurvey)	1st Bill 580) 40/\$45 \$120 \$30	
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions NA 2103213 Claimant's Particulars:- Priver/Owner:	Invoic 1) AR: / 2) DA: I 3) TF: T 4) FT: F 5) FT: F For ele 6) TR: I	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$ owing Fee \$ ollow-Through Survey ollow-Through Survey (Resurvey) siming against INC Only (wef 10 Jan 200) Re-inspection	1st Bill 880) 40/\$45 \$120 \$30 25) \$75	
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions NA 2103213 Claimant's Particulars:- Driver/Owner:	Invoice 1) AR: // 2) DA: I 3) TF: T 4) FT: F 5) FT: F For ele 6) TR: I 7) N1: I	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$ owing Fee \$ ollow-Through Survey ollow-Through Survey (Resurvey) siming against INC Only (wef 10 Jan 20) Re-inspection dae DA + SMRT Survey	1st Bill 580) 40/\$45 \$120 \$30 25)	
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions NA 2103213 Claimant's Particulars:- Driver/Owner: Contact No: Damaged Portion:	Invoice 1) AR: 7 2) DA: 1 3) TF: T 4) FT: F 5) FT: F For cle 6) TR: I 7) N1: I 8) NTUC OD: 2	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$ owing Fee \$ ollow-Through Survey (Resurvey) siming against INC Only (wef 10 Jan 20) Re-inspection dae DA + SMRT Survey C Additional Services:-	1st Bill 880) 40/\$45 \$120 \$30 25) \$75 \$160	
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions NA 2103213 Claimant's Particulars:- Priver/Owner: Contact No: Damaged Portion:	Invoice 1) AR: A 2) DA: I 3) TF: T 4) FT: F 5) FT: F For ele 6) TR: I 7) N1: I 8) NTUC OD: *N5:	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$ owing Fee \$ ollow-Through Survey (Resurvey) aiming against INC Only (wef 10 Jan 200) Re-inspection dae DA + SMRT Survey C Additional Services:- Courtesy Car / Tpt Allowance	1st Bill 880) 40/\$45 \$120 \$30 25) \$75	
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions Claimant's Particulars:- Oriver/Owner: Contact No: Damaged Portion: OC Checked by (Engr-In-Charge):	Invoice 1) AR: 7 2) DA: 1 3) TF: T 4) FT: F 5) FT: F For cle 6) TR: I 7) N1: I 8) NTUC On: *N5: *N6: *N7:	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$ owing Fee \$ ollow-Through Survey ollow-Through Survey (Resurvey) siming against INC Only (wef 10 Jan 20) Re-inspection dae DA + SMRT Survey C Additional Services:- Courtesy Car / Tpt Allowance Repair Co-ordination Post Repair Inspection	1st Bill 580) 40/\$45 \$120 \$30 25) \$75 \$160 \$\$5 \$10 \$25	
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions Claimant's Particulars:- Oriver/Owner: Contact No: Damaged Portion: OC Checked by (Engr-In-Charge): Auditors' Comments:-	Invoice 1) AR: A 2) DA: I 3) TF: T 4) FT: F 5) FT: F For cl. 6) TR: I 7) N1: I 8) NTUC Ol)* *N5: I *N6: *N7: *N8:	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$ owing Fee \$ ollow-Through Survey (Resurvey) aiming against INC Only (wef 10 Jan 200) Re-inspection dae DA + SMRT Survey C Additional Services Courtesy Car / Tpt Allowance Repair Co-ordination Post Repair Inspection DV / Collect Excess Coordination	1st Bill 580) 40/\$45 \$120 \$30 25) \$75 \$160 \$55 \$10 \$25 \$55	
3) Upload Resurvey Photo [Repair Cost > \$30 Injury: Date/Time Actions	Invoice 1) AR: A 2) DA: I 3) TF: T 4) FT: F 5) FT: F For ele 6) TR: I 7) N1: I 8) NTUC OD* *N5: I *N6: *N7: *N8: TP (N	Accident Reporting (\$30); Damage Assessment (\$100); INC (\$ owing Fee \$ ollow-Through Survey ollow-Through Survey (Resurvey) siming against INC Only (wef 10 Jan 20) Re-inspection dae DA + SMRT Survey C Additional Services:- Courtesy Car / Tpt Allowance Repair Co-ordination Post Repair Inspection	1st Bill	Amt (\$) Add Bill



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/06/2021 13:50 (SGT) Date of Accident 25/06/2021 12:50 (SGT) **Exact Location of Accident** CTE, Singapore Additional Location Information TOWARDS AYE (TUAS) BEFORE CAIRNHILL EXIT Country/State of Loss

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMX6216A

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NADHIR OTHMAN NRIC No SXXXX672Z **Email Address** X543210H@GMAIL.COM Mobile Phone No (Phone) +65-81614857 Alternative Phone No +65-81614857

VEHICLE PARTICULARS

Manufacturer Honda Model Shuttle Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Type of Coverage Comprehensive Fleet Policy No Policy Number DMPCSNW00020572100 Cover Note Number

1496

DRIVER

CC

Name of Driver NADHIR OTHMAN NRIC No SXXXX672Z

Date Of Birth 13/09/1990 Occupation Indoor Date Of Driving Pass 10/07/2009 Driving experience 11 YEARS AND 11 MONTHS Gender Male Mobile Number (Phone) +65-81614857 Alt. Phone Number +65-81614857 **Email Address** X543210H@GMAIL.COM Address BLK 262 TOA PAYOH EAST #16-14 Address complement Postcode 310262 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 4 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 5 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name NGAI YEE SENG Gender Male PASSENGER 2 Name TONG SIEW PING Gender Female PASSENGER 3 Name KARRIE NGAI PUI YU Gender Female PASSENGER 4 Name ZEANNE NGAI NADHIR Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO STATEMENT. ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCJ79K Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number **SLF9910R** Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLX9093D Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person Address

NADHIR OTHMAN



Accident report SN09216S0005

Page 3 of 23

Address Complement	
Post Code	
Approximate Age Years Old	
Injuries Sustained	BODY
Injured person in which vehicle?	
Were seat belts worn?	
Was this injured conveyed to hospital by ambular	
	110
INJURED 2	
Name of injured person	TONG SIEW PING
Address	**************************************
Address Complement	DAGGERIO DE CONTROL - 1-
Post Code	***************************************
Approximate Age Years Old	(Free Free Co. 100 at Free Co.
Injuries Sustained	
Injured person in which vehicle?	SMX6216A
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambular	nce? No
INJURED 3	
Name of injured person	KARRIE NGAI PUI YU
Address	-
Address Complement	
Post Code	
Approximate Age Years Old	
Injuries Sustained	BODY
Injured person in which vehicle?	
Were seat belts worn?	
Was this injured conveyed to hospital by ambular	nce? No
INJURED 4	
Name of injured person	ZEANNE NGAI NADHIR
Address	
Address Complement	**************************************
Post Code	
Approximate Age Years Old	-
Injuries Sustained	
Injured person in which vehicle?	SMX6216A
Were seat belts worn?	
Was this injured conveyed to hospital by ambular	nce?No

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Driver's Signature (If driver is not the policyholder) / Date Witnessed by Reporting Centre Personnel

Sketch Plan

Vehicle A: SM x 6216A

Vehicle B: SCJ 79 K

Vehicle C: SLF 9910 R

Vehicle D: SLX 9093 D

7		
^	STATED DATE & TIME . I VEHILLE A SMX 6216 0 WAS COMMENT	
	A DRIVING HICHGE CT	E
	DI THUE FAIL ON THE DI THUE SEHICLE C 271	7910R
IN FRONT	DEALE I LETTONED INIT , SODDENIA	
	SCJ 79K COULD NOT STOP IN TIME AND HIT ONTO MY VEHILLE CAUSING MY	VEHI
10 RE PUI	HEO FORWARD AND HIT ONTO YEHILLE C SLF9910R. THEN I CAME OUT OF M	y CAR
& REALISED	TOWNER D SOL 13 D INVOCACIO IN THIS HELIDE	itu.
TOTAL OF	4 VEHICLES WERE INVOLVED IN THIS CHAIN COLLISION	
		3/19-00-

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

42

Witnessed by Reporting Centre Personnel



CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Motor Private Car

MX1F

SN

AN0644A Cov. Type C

CERTIFICATE OF INSURANCE otor Vehicles (Third-Party Risks and Compensation) Act (Chapter 14 Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) pter 189)

Motor Vehicles (Third-Party Risks) Rules. 1959 (Malaysia)

CERTIFICATE No.

DMPCSNW00020572100

Engine No.: L15B6020488

Cha. No. GK82100400

1 Index Mark and Registration

SMX6216A

AUTOSAFE

Number of Vehicle

NADHIR OTHMAN

Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment

22/01/2021 (00:00:00)

Named Drivers Ex Sect. I

S\$500.00

Additional Ex Other than Named Drivers:

4. Date of Expery of Insurance

21/01/2022

Ex Sect 1 - Age <= 25 Ex Sect. I - Age >= 26 \$\$3,000.00 \$\$500.00

* Age as at date of accident

EX ON WINDSCREEN .

S\$100.00

5. Persons or Classes of Persons entitled to drive

(a) The Policyholder.(b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6 Lymitations as to use *

Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability that, speed-testing, the carnage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.

One time Waiver of Excess for the first \$\$500 will apply to the Insured and Named Drivers in the event

of Own Damage Claim at our Authorised Workshops for each Policy Year

HIRE PURCHASE CO.: STANDARD CHARTERED BANK(S)LIMITED

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

ENTERRAIS

GST/Cd/Reg Issued By: CAR HOUSE ENTERPRISE S PTE LTD For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Authorised Signatory

China Taiping Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200208384E) 😭 3 Anson Road #16-00 Springleaf Tower Singapore 079909

Q63896111

6222 1033

www.sg.cntaiping.com

Date of Accident	25/06/21 Accident Time: 1250 (24-HR-Format)
Accident Place	: CTE Tord ATE (Tuas) before Cairnhill Exit
Vehicle No. (Car Plate No.)	: SMX 6216A Make/Model: H. Shuttle
,	China Talping Policy No: DMPCSHW00020572100
Insurance Company	Nadhir Othman S90336727
Owner or Company Name / IC No.	Owner's Hp <u>8161 4857</u> Company Tel
Owner or Company Contact No.	: Nadhir Othman
DRIVER'S Name/IC No.	: 13/09/1990 DRIVER'S License Pass Date: 10/07/2019
DRIVER'S Date of Birth	
Relationship of Owner & Driver	: Spouse / Parents / Children / Sibling / Employee / Others: _Owner
DRIVER'S Address	Blk 262 Toa Payoh East #16-14 5310262
DRIVER'S Contact No./ Alt No.	: 1)2)
DRIVER'S Occupation	NDOORY OUTDOOR (e.g. working inside or outside office)
Email Address	: X543210h@gmail.com
Weather & Road Surface	: CLEAR & DRY RAINING & WET / AFTER RAIN & WET
Reporting Type	: Reporting Only Claim Other Party / Claim Own Insurance
Number of Passengers (Including D	Driver): 5
Was there any video Captured by	car camera: YES /NO
Exact purpose for which vehicle w	as being used at the time of accident: Private Use / Work Purpose
Any injury (If YES, Pleas state): 4	Person
	Other Party Driver's Particular (if any)
Vehicle No B : 5CJ	79 K Vehicle No C : SLF 9910R
Vehicle Make/Model : Hyun	doi Vehicle Make/Model : Toyota
Name Driver :	Name Driver :
IC No. Driver/Contact: :	IC No. Driver/Contact: :
relycle NOD: SLX900	13D Toyota
Passenger's name & gender:	
NGAI YEE SENG X M	Workshop email: xinhuaworkshop@gmail.com
TONG SIEW PING FE	EMALE
KARRIE NGAI PUI YU T	EMALE
PERNNE NGAL NADHUR F	Emals