



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883 ON BEHALF OF LIM BOON JUI			Ref: CS/TP21007132/Utf3e2 Date: 12/07/2021 Code: TP149	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SLF 4254J	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	29/06/2021	
2. Vehicle Particulars & Condition				
	Make & Model	KIA SORENTO (A)	c.c	2199
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KNAPH81BMG5240039	Colour	GREY
	Odometer	104255 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/60 R18	MICHELIN	6 mm
	L/H Front Tyre	235/60 R18	MICHELIN	6 mm
	R/H Rear Tyre	235/60 R18	MICHELIN	6 mm
	L/H Rear Tyre	235/60 R18	MICHELIN	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	22/06/2021	Inspection Date	29/06/2021
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days