

ASS. REC. BY:

Steve

CS3/AIG 2100714S/Egf3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

9016542657SG

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SME 7746E

Yr Regn:

16/19/18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or

Make:

Toyota AMIS

c.c.

1598

Colour:

Grey

A/C:

Insured / Std / Nil / N

Sp. Reading

56241

T/Radio: Insured / Std / Nil / N

Eng/No:

C/No:

MR 053RE14: 04591679

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

(1)

BS / QUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

26/6/21

D.O.I.

30/6/21

Survey held at

Tian Siang Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

05/07/21 Submit DAR.

Date/Time, File, Pass to?



: Prel. Report

05/07 Typist



: Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (\$



: Wash and (\$

Photos

Others

TOTAL

3rd Form:

MER-DAR

Work Sum / L.B. /

### Front Portion

| NAC  | INC    | Item                                   | CON | AC | Qty |
|------|--------|----------------------------------------|-----|----|-----|
| 1001 | 991886 | Frt Number Plate                       | BT  | ✓  |     |
| 1002 | 991887 | Frt Number Plate Base                  | CRU | ✓  |     |
| 1003 | 991889 | Frt Number Plate Garnish               |     |    |     |
| 1004 | 991300 | Frt Bumper                             | BR  | ✓  |     |
| 1005 | 992341 | Frt Bumper Clips                       | ACC | ✓  |     |
| 1006 | 991325 | Frt Bumper Bracket                     |     |    |     |
| 1007 | 991462 | Frt Bumper Side Retainer               | BR  | ✓  | 2   |
| 1008 | 991433 | Frt Bumper Reinforcement               |     |    |     |
| 1009 | 991318 | Frt Bumper Beam                        |     |    |     |
| 1010 | 991468 | Frt Bumper Sponge                      | BR  | ✓  |     |
| 1011 | 991427 | Frt Bumper Protector                   |     |    |     |
| 1012 | 991420 | Frt Bumper Pad                         |     |    |     |
| 1013 | 991363 | Frt Bumper Grille <i>lower</i>         | BR  | ✓  |     |
| 1014 | 991301 | Frt Bumper Moulding                    |     |    |     |
| 1015 | 991407 | Frt Bumper Lower Spoiler               |     |    |     |
| 1016 | 991438 | Frt Bumper Sensor                      |     |    |     |
| 1017 | 995100 | Frt LH Bumper Fog Lamp Cover           |     |    |     |
| 1018 | 991355 | Frt RH Bumper Fog Lamp Cover           |     |    |     |
| 1019 | 995079 | Frt LH Bumper Fog Lamp                 |     |    |     |
| 1020 | 995080 | Frt RH Bumper Fog Lamp                 |     |    |     |
| 1021 | 991793 | Frt Grille                             | BR  | ✓  |     |
| 1022 | 991328 | Frt Grille Emblem                      | ACC | ✓  |     |
| 1023 | 991799 | Frt Grille Chrome Moulding             | BR  | ✓  |     |
| 1024 | 991222 | Frt Apron Panel                        |     |    |     |
| 1025 | 992013 | Frt Support Panel                      |     |    |     |
| 1026 | 992025 | Frt Support Panel Top Garnish Cover    |     |    |     |
| 1027 | 992416 | Horn                                   |     |    |     |
| 1028 | 991277 | Frt Brace Panel                        |     |    |     |
| 1029 | 995153 | Frt LH Headlamp Assy                   | CRU | ✓  |     |
| 1030 | 991821 | Frt RH Headlamp Assy                   | CRU | ✓  |     |
| 1031 | 995088 | Frt LH Side Lamp                       |     |    |     |
| 1032 | 995089 | Frt RH Side Lamp                       |     |    |     |
| 1033 | 990248 | Bonnet                                 |     |    |     |
| 1034 | 991328 | Bonnet Emblem                          |     |    |     |
| 1035 | 990287 | Bonnet Lock                            |     |    |     |
| 1036 | 990285 | Bonnet Insulator                       |     |    |     |
| 1037 | 990273 | Bonnet Flange                          |     |    |     |
| 1038 | 990261 | Bonnet Damper                          |     |    |     |
| 1039 | 990305 | Bonnet Rubber                          |     |    |     |
| 1040 | 990252 | Bonnet Cable                           |     |    |     |
| 1041 | 990311 | Bonnet Stand                           |     |    |     |
| 1042 | 990119 | Air Con Condenser                      |     |    |     |
| 1043 | 990122 | Air Con Fan Assy                       |     |    |     |
| 1044 | 990124 | Air Con Suction Pipe (Low Pressure)    |     |    |     |
| 1045 | 990118 | Air Con Suction Hose                   |     |    |     |
| 1046 | 990133 | Air Con Discharge Pipe (High Pressure) |     |    |     |
| 1047 | 990114 | Air Con Discharge Hose                 |     |    |     |
| 1048 | 990149 | Air Con Liquid Pipe                    |     |    |     |
| 1049 | 995066 | Air Con Receiver Drier                 |     |    |     |
| 1050 | 990111 | Air Con Compressor Assy                |     |    |     |
| 1051 | 995294 | Air Con Belt                           |     |    |     |
| 1052 | 995074 | Radiator                               |     |    |     |
| 1053 | 992738 | Radiator Cowling                       |     |    |     |
| 1054 | 992742 | Radiator Fan Assy                      |     |    |     |
| 1055 | 992745 | Radiator Fan Clutch                    |     |    |     |
| 1056 | 992758 | Radiator Hose Top                      |     |    |     |
| 1057 | 992757 | Radiator Hose Bottom                   |     |    |     |
| 1058 | 992741 | Radiator Expansion Tank                |     |    |     |
| 1059 | 990151 | Air Duct                               |     |    |     |
| 1060 | 990070 | Air Cleaner Assy                       |     |    |     |
| 1061 | 990056 | Air Cleaner Hose                       |     |    |     |
| 1062 | 990039 | Air Cleaner Resonator                  |     |    |     |
| 1063 | 991712 | Frt Exhaust Manifold                   |     |    |     |
| 1064 | 991713 | Frt Exhaust Manifold Cover             |     |    |     |
| 1065 | 991054 | Frt Exhaust Manifold Sensor (Oxygen)   |     |    |     |
| 1066 | 991714 | Front Exhaust Pipe                     |     |    |     |
| 1067 | 990219 | Battery                                |     |    |     |
| 1068 | 990224 | Battery Cover                          |     |    |     |

## Vehicle No:

SME 7746E

| NAC  | INC    | Item                         | Col | AC | QTY |
|------|--------|------------------------------|-----|----|-----|
| 1071 | 992205 | Fuse Box                     |     |    |     |
| 1072 | 994011 | Delay Box                    |     |    |     |
| 1073 | 995053 | Wiper Washer Tank            |     |    |     |
| 1074 | 995052 | Wiper Washer Tank Motor      |     |    |     |
| 1075 | 990159 | Alternator Assy              |     |    |     |
| 1076 | 990160 | Alternator Belt              |     |    |     |
| 1077 | 992683 | Power Steering Pump          |     |    |     |
| 1078 | 992669 | Power Steering Belt          |     |    |     |
| 1079 | 994431 | Power Steering Cooler Pipe   |     |    |     |
| 1080 | 992692 | Power Steering Hose          |     |    |     |
| 1081 | 990010 | ABS Pump Control Unit        |     |    |     |
| 1082 | 990427 | Brake Master Pump Assy       |     |    |     |
| 1083 | 990403 | Brake Booster Pump Assy      |     |    |     |
| 1084 | 991005 | Engine Top Cover             |     |    |     |
| 1085 | 991011 | Engine Under Cover           |     |    |     |
| 1086 | 990946 | Engine Mounting              |     |    |     |
| 1087 | 990949 | Engine Mounting Frt          |     |    |     |
| 1088 | 990950 | Engine Mounting LH           |     |    |     |
| 1089 | 990952 | Engine Mounting RH           |     |    |     |
| 1090 | 990951 | Engine Mounting Rear         |     |    |     |
| 1091 | 992234 | Gear Box Mounting            |     |    |     |
| 1092 | 991520 | Frt LH Chassis Member        |     |    |     |
| 1093 | 991520 | Frt RH Chassis Member        |     |    |     |
| 1094 | 990728 | Frt Vertical Cross Member    |     |    |     |
| 1095 | 991863 | Frt Lower Cross Member       |     |    |     |
| 1096 | 995070 | Frt LH Fender                |     |    |     |
| 1097 | 995072 | Frt LH Fender Inner Panel    |     |    |     |
| 1098 | 995147 | Frt LH Fender Lamp           |     |    |     |
| 1099 | 995148 | Frt LH Fender Protector      |     |    |     |
| 1100 | 991740 | Frt LH Fender Inner Shield   |     |    |     |
| 1101 | 995179 | Frt LH Mudflap               |     |    |     |
| 1102 | 995170 | Frt LH Wheel Rim             |     |    |     |
| 1103 | 994025 | Frt LH Rim Cover             |     |    |     |
| 1104 | 995065 | Frt LH Tyre                  |     |    |     |
| 1105 | 995071 | Frt RH Fender                |     |    |     |
| 1106 | 991739 | Frt RH Fender Inner Panel    |     |    |     |
| 1107 | 991744 | Frt RH Fender Lamp           |     |    |     |
| 1108 | 991752 | Frt RH Fender Protector      |     |    |     |
| 1109 | 991740 | Frt RH Fender Inner Shield   |     |    |     |
| 1110 | 991884 | Frt RH Mudflap               |     |    |     |
| 1111 | 992087 | Frt RH Wheel Rim             |     |    |     |
| 1112 | 994025 | Frt RH Rim Cover             |     |    |     |
| 1113 | 995065 | Frt RH Tyre                  |     |    |     |
| 1114 | 992093 | Frt Windscreen Glass         |     |    |     |
| 1115 | 992117 | Frt Windscreen Rubber        |     |    |     |
| 1116 | 992108 | Frt Windscreen Moulding      |     |    |     |
| 1117 | 992098 | Frt Windscreen Sealant       |     |    |     |
| 1118 | 991019 | ERP Bracket                  |     |    |     |
| 1119 | 991020 | ERP Unit                     |     |    |     |
| 1120 | 992140 | Frt Wiper Arm                |     |    |     |
| 1121 | 992142 | Frt Wiper Blade              |     |    |     |
| 1122 | 995045 | Wiper Panel Garnish          |     |    |     |
| 1123 | 991126 | Firewall Panel               |     |    |     |
| 1124 | 990753 | Dashboard Assy               |     |    |     |
| 1125 | 992282 | Glove Box Cover              |     |    |     |
| 1126 | 992281 | Glove Box Compartment        |     |    |     |
| 1127 | 994483 | Steering Wheel Airbag        |     |    |     |
| 1128 | 994485 | Steering Wheel Airbag Sensor |     |    |     |
| 1129 | 990749 | Dashboard Airbag             |     |    |     |
| 1130 | 990750 | Dashboard Airbag Sensor      |     |    |     |
| 1131 | 990029 | Airbag Control Unit          |     |    |     |
| 1132 | 990864 | Frt Driver Seat              |     |    |     |
| 1133 | 991922 | Frt RH Seat Belt Assy        |     |    |     |
| 1134 | 991899 | Frt Passenger Seat           |     |    |     |
| 1135 | 995182 | Frt LH Seat Belt Assy        |     |    |     |
| 1136 | 990247 | Sticker                      |     |    |     |

3 repair days

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the CAA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                                 |                            |
|---------------------------------|----------------------------|
| Date of Submission              | 28/06/2021 15:28 (SGT)     |
| Date of Accident                | 26/06/2021 17:20 (SGT)     |
| Exact Location of Accident      | Singapore                  |
| Additional Location Information | BLK 210 PETIR ROAD CARPARK |
| Country/State of Loss           | Singapore                  |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SME7746E             |
| INSURED/POLICYHOLDER        |                      |
| Is company?                 | No                   |
| Name Of Registered Owner    | TEO TECK WAH         |
| NRIC No                     | SXXXXX036C           |
| Email Address               | info@liangyifood.com |
| Mobile Phone No             | (Phone) +65-98804877 |
| Alternative Phone No        | +65-98804877         |

### VEHICLE PARTICULARS

|                                                                              |                           |
|------------------------------------------------------------------------------|---------------------------|
| Manufacturer                                                                 | Toyota                    |
| Model                                                                        | Corolla                   |
| Variant                                                                      | -                         |
| Exact purpose for which vehicle was being used at time of accident           | Private use               |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category                                                             | Private car               |
| Transmission                                                                 | Auto                      |
| CC                                                                           | 1600                      |

### INSURANCE COMPANY

|                           |                                        |
|---------------------------|----------------------------------------|
| Name of Insurance Company | NTUC Income Insurance Co-operative Ltd |
| Type of Coverage          | Comprehensive                          |
| Fleet Policy              | No                                     |
| Policy Number             | 5119171902 (CLASSIC)                   |
| Cover Note Number         | -                                      |

### DRIVER

|                |                                  |
|----------------|----------------------------------|
| Name of Driver | SEETOH PING BOON@SEETOH LEE KIAT |
| NRIC No        | SXXXXX641H                       |

|                                                              |                            |
|--------------------------------------------------------------|----------------------------|
| Date Of Birth                                                | 19/03/1989                 |
| Occupation                                                   | Outdoor                    |
| Date Of Driving Pass                                         | 26/04/2010                 |
| Driving experience                                           | 11 YEARS AND 2 MONTHS      |
| Gender                                                       | Male                       |
| Mobile Number                                                | (Phone) +65-93217250       |
| Alt. Phone Number                                            | -                          |
| Email Address                                                | jacky13579@hotmail.com     |
| Address                                                      | BLK 625 SENJA ROAD #23-146 |
| Address complement                                           | -                          |
| Postcode                                                     | 670625                     |
| Is the driver the policyholder?                              | No                         |
| If No, Relationship of the Driver with the Insured           | Relative                   |
| Does Driver Own Other Vehicles?                              | No                         |
| Vehicle Registration Number of Other Vehicle Owned by Driver | -                          |
| Insurance Company of Other Vehicle Owned by Driver           | -                          |

#### GENERAL INFORMATION OF THE ACCIDENT

|                    |                          |
|--------------------|--------------------------|
| Type of Accident   | Collision - Head to Rear |
| Weather Conditions | Clear                    |
| Road Surface       | Dry                      |

#### OTHER INFORMATION

|                                                                                                     |     |
|-----------------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in the accident?                                                   | No  |
| Number of vehicles involved in the accident                                                         | 2   |
| Was anybody injured in the Accident?                                                                | Yes |
| Was any injured conveyed to hospital by ambulance?                                                  | No  |
| Was any other vehicle or property damaged?                                                          | Yes |
| Number of Passengers (Including Driver)                                                             | 1   |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No  |

#### DETAILS OF POLICE ACTION

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom?                     | -  |

#### CIRCUMSTANCES OF ACCIDENT

#### REFER STATEMENT

(ATTENDED BY: JAMES NG)

#### ATTACHMENT(S)

|                                                   |                                |
|---------------------------------------------------|--------------------------------|
| Are accident photos available for attachment?     | Yes                            |
| Was there any video captured by Car Camera?       | Yes                            |
| Reasons for not uploading a video of the accident | CANNOT BE UPLOADED INTO SYSTEM |
| Was there any audio recorded?                     | No                             |

#### DETAILS OF OTHER VEHICLE PROPERTY

|                             |                    |
|-----------------------------|--------------------|
| Vehicle Registration Number | GBH6271D           |
| Vehicle Manufacturer        | Toyota             |
| Vehicle Model               | Dyna               |
| Vehicle Variant             | -                  |
| Vehicle Colour              | -                  |
| Vehicle Category            | Commercial vehicle |
| Name of Driver              | -                  |

Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

### INJURED PERSONS DETAILS

#### INJURED 1

Name of injured person  
Address  
Address Complement  
Post Code  
Approximate Age Years Old  
Injuries Sustained  
Injured person in which vehicle?  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?

SEETOH PING BOON@SEETOH LEE KIAT  
BLK 625 SENJA ROAD #23-146  
-  
670625  
32  
NECK INJURY WITH 2 DAYS MC  
SME7746E  
Yes  
No

### WITNESS DETAILS

#### WITNESS 1

Name  
Phone  
Email

JESSE  
(Phone) +65-97969395  
-

SKETCH PLAN

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/road packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

20/07/2021

NG WING KIN JAMES  
admin.vac@vicom.com.sg



A: SME7746E

B: GBH6271D

Describe Circumstances of the Accident

As I am turning out to drive out of the carpark, a lorry (G15H6271D) suddenly reverse and hit my car. I have ~~not~~ to heard the driver to inform him that I am nearby and seeing that he wasn't stopping, I immediately reverse to avoid him but wasn't fast enough.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

20 JUN 2021



NG WING KIN JAMES  
admin.vac@vicom.com.sg