

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. 2806463267SG


Sum Insured: _____ Excess: 1700

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$102K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.8.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

01/07/21 @10.12am revert to AIG via Merimen.

01/07/21 @11.35am Kok Chong informed C/A & revise spray paint to \$450/- via Merimen.

01/07/21 @12.42pm Informed Candy C/A & ex: \$1700 & spray paint revise to \$450/- by email.

Kenneth re-finalised final fig \$5314.60 (Red \$2705, 34%)

Date/Time, File Pass to?

☐

: Prel. Report

11/05/08 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Report Format: MER-OD

Lump Sum / I.B.I: (\$ 5314.60)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Veh No: PKW5517S Yr Regn: 11, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mv E250 c.c. 1991

Colour: M. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 52560 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 2120382B 212079

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tire Size: F: 245/40ZR18

R: 265/35ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 28/6/21

Survey held at

Rear

R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 30/6/2021

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Fr body

The U/C / Chassis frame / Body Structure affected due to collision.



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/06/2021

ESTIMATE

NO : QUOT202106-000042(00)

DATE : 29/06/2021

POLICY NO : 999995580

VEH REG NO : SKW5517S

MAKE/MODEL : MERCEDES BENZ E250 SEDAN
EDITION E (R18 LED)

CHASSIS NO : WDD2120362B212079

ENGINE NO : 27492030443394

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SKW5517S

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Front door -- RH	1	1,280.00	1,280.00 ✓
2 Front door weatherstrip -- RH	1	198.00	198.00 ✓
3 Side mirror assy -- RH	1	1,850.00	1,850.00 ✓
4 Front fender - RH (Aluminium)	1	590.00	590.00 ✓
5 Front door 'EDITION' emblem - RH	1	68.00	68.00 ✓
6 Front sport rim - RH	1	1,150.00	1,150.00 X
			5,136.00
		Add 10%	513.60
			5,649.60
LABOUR			
7 To transfer RH front door interior mechanism to new door	1	150.00	150.00 60d
8 To check and rectify wiring system	1	100.00	100.00 2d
9 To panel beat RH front door pillar, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00 40d 65d
10 To putty & spray paint on affected areas	1	1,200.00	1,200.00 65d
11 To computerise check wheel alignment	1	120.00	120.00 X
			2,370.00
		TOTAL	S\$ 8,019.60
		ADD GST @ 7%	561.37
		GRAND TOTAL	S\$ 8,580.97

SINGAPORE DOLLAR EIGHT THOUSAND FIVE HUNDRED EIGHTY AND CENTS NINETY-SEVEN ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/06/2021 18:00 (SGT)
Date of Accident	01/06/2021 06:30 (SGT)
Exact Location of Accident	River Valley, Singapore
Additional Location Information	Along River Valley road
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW5517S
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
Company Reg No	1XXXXXX78Z
Email Address	benny.chong@daimler.com
Mobile Phone No	(Phone) +65-68498118
Alternative Phone No	(Office) +65-68498118

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E250 SEDAN EDITION E (R18 LED)
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1991

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	NA

DRIVER

Name of Driver	KANG JAE YEON
NRIC No	SXXXX311G

ACCIDENT DIAGRAM

Ver 30042021



Vehicle A: SKW 5517S.

Vehicle B: FBF 4348R.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SAIFULLAH S/O SYED MASOOD

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 238572
Tel No: 1800-7350999



T/20210601/2507

1 of 3

Report No. T/20210601/2007

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/06/2021 08:37		Video Report No.: E/20210601/0023		Station Diary No.: 24
Informant's Particulars				
Name of Informant: KANG JAE YEON		Address: BLK 118 KIM SENG ROAD #25-10 SINGAPORE 239435		
ID Type / ID No.: NRIC NO / S2722311G		Contact No.: Home/Office: Mobile: 98159584		
Nationality: KOREAN, SOUTH		Email:		
Sex: Female	Age: 54	Date of Birth: 21/06/1966	Type of Informant: Driver	
Race: Korean		Language:	Institution / School Name:	
Occupation: Company director		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/06/2021 06:30	Type of Location: Straight Road
Location: KIM SENG ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 40 Km/h	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBF4348R	Motorcycle				Slightly Damaged	2
SKW5517S	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20210601/2007

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

2 of 3

Report No. T/20210601/2007

CONTINUATION OF REPORT

Name	Unknown		ID No.	NIL
Related Vehicle	FBF4348R (Motorcycle)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Driver				
Name	KANG JAE YEON		ID No.	S2722311G
Related Vehicle	SKW5517S (Car)		Contact No.	98159584
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

At about 0630 to 0700hrs, I was driving Mercedes Benz E250 bearing registration plate: SKW5517S. I had rented the vehicle under car leasing company (Daimler Fleet Management). I had exited Trillium Condominium and was turning left towards River Valley Road. At that time, there was a motorcycle coming. As it was a two-lane traffic, I thought the said bike (FBF4348R) would have stayed on the outer most lane. As such, I turned left and stayed on the left most lane. However, the said bike hit onto the front driver side of the door. The rider and pillion of the bike was later conveyed to Singapore General Hospital, I did not sustain any physical injuries.

The Traffic Police attended to me and I am lodging this report to facilitate in their investigation. They can contact Seri at mobile number (91500968). She was driving behind when the accident took place and she alighted and informed me that she has a in-car camera which captured the incident.