



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM21007183/Uga3q2 Date: 20/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8236S	Veh. Inspected	SLS 5162R	
Policy No.	P2419138	Coverage (\$)	0.00	
Claim No.	S1M03C8N	Excess (\$)	0.00	
Assign From		Assign Date	30/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN X-TRAIL (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JN1JANT32Z0010151	Colour	ORANGE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R19	BRIDGESTONE	6 mm	
L/H Front Tyre	225/55 R19	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/55 R19	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/55 R19	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.THE UNDERCARRIAGE & CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/06/2021	Inspection Date	30/06/2021	
Survey held at	NINETEEN AUTOWERKS PTE. LTD. 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			30 Working Days	