

2/23/2012

R1tf-1

ASS. REC. BY: RASUL

REF: CS3/MSG 19007570/ ~~16207~~

Special Instruction:

Surveyor: Hwaie Jie

ASSIGNMENT (Office)

30/6/2021 1:44 PM

urimu

From (Person): ~~Josiane Let Hong Kwai~~ of MSG

Date/Time: ~~29.4.19 4:28 PM~~

Estimated Cost: DOUGLAS ONG Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: WXA 312

Insured: YN 6514A

at Workshop m/s Sincere Lead Automotive

Tel: 9815 8858

of 38 woodlands Ind Park E1 #05-13

Policy No: B 2862 5376 MKC

Claim No: 591779

Sum Insured: _____

Excess: _____

Make of Veh:
(Client's Record)

D.O.A. 18.4.19

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 20.4.19 9:56 a.m

Person Contacted: _____

Raymond

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate (X)	Inspection: 38 woodland #05-16
	WXA 312 - X		
	YN 6514A - X		

REF: MS16

Hwee Jie

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / (P) / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No. WXA312 Yr Regn: 03 / 19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Pulsar N3200 c.c. 200
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 548 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: PMNNS200NJML03913
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / SRM / STD A/Rim or _____
 Tyre Size: F: 100/80-17
 R: 130/70-17

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

<u>N/S</u>	<u>O/S</u>

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Nylogrip Zapper
 Front 6 mm R/Bal. 6 mm
 L/Bal. - mm L/Bal. - mm
 D.O.A. 18/4/19 D.O.I. 30/4/19
 Survey held at Sincere Lead
 Des. of Damages: Frnt / Rear O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PRS
	Range: \$2000-\$3000 3 days <i>[Signature]</i> 2/5/2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to?
 Days Of Repair: 3
 Resurvey No. of Trip: -
 Survey Fee: 120
 Transportation: _____
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)
 Report Format: PRE
 Lump Sum / I.B.I.: (\$)
 TOTAL 130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Apr 2019		29 Apr 2019 16:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	JA LAN TIONG PTE LTD, Co. Reg. No.: 199303540G	
Main Claimant:	LEOW CHUAN CHIEW, ID: G2941409U	
Vehicle Reg. No.:	WXA312	Date of Loss: 18/04/2019 07:00 - :59 [231 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 591779	Policy/Cover Note No.: B28625376MKC (Comprehensive) Coverage: 29/10/2018 - 28/10/2019
Vehicle Reg. No. (Insured):	YN6514A	Policy No. (Claimant): Excess:
Repairer:	Sincere Lead Automotive (Woodlands 3) 38 Woodlands Ind. Park E1 #05-13, 757710 Woodlands - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/04/2019]	
Driver/Custodian (Insured):	KARUNANITHI DHARMALINGAM (), NRIC: G5227677U, Tel: +6583583100 Email:	
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:100%. CONTACT: MR RAYMOND CHUA 9815 8858	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
---------------------------------	--------------------------	-----------------------------------

There are no mail for this case.

ALL ASSOCIATED TASKS										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	
No results.										



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

NSTXODMN

No. Pendaftaran : WXA312
No. ID : 940321085763
Nama Pemunya Berdaftar : LEOW CHUAN CHIEW
Alamat : NO 40 LORONG CEMPAKA 1 FELDA IJOK
34120 SELAMA PERAK

No. Chasis/No. Enjin : PMNNS200NJML03913 / JLYCJE53732
Buatan>Nama Model : MODENAS / PULSAR-NS200FI NS200
Keupayaan Enjin : 200
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : MOTOSIKAL
Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2018
Tarikh Pendaftaran : 31/03/2019
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999



T/20190422/2106

1 of 3

Report No. T/20190422/2106

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
22/04/2019 16:23

Vide Report No.:

Station Diary No.:
164

Informant's Particulars

Name of Informant: LEOW CHUAN CHIEW			Address: 09 Jalan 29 Seroja Johor Jaya		
ID Type / ID No.: FIN NO / G2941409U			Contact No.: Home/Office: Mobile: 9132 5116		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 25	Date of Birth: 21/03/1994	Type of Informant: Rider		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: MECHANICAL TECHNICIAN			Driving Licence Information: Class: 2B		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 18/04/2019 07:20	Type of Location: X-Junction
Location: Along Road 1 JOO KOON WAY JOO KOON CIRCLE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
WXA312	Motorcycle	BAJAJ CHETAK	PULSAR NS 200	Black	Seriously Damaged	0
YN6514A	Trailer Truck	MITSUBISHI		White	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



1/20190422/2106

Police Station Of Origin:
Nanyang N.P.C.
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

2 of 2

Report No: 1/20190422/2106

CONTINUATION OF REPORT

Rider			
Name	LEOW DHUAN CHEW	ID No	G2941409U
Related Vehicle	WXA312 (Motorcycle)	Contact No	9132 5116
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	18/04/2019	Date Discharge	18/04/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 18/04/2019 at about 0720hrs, while proceeding to work, I was travelling along Joo Koon Way. When approaching the junction at Joo Koon Circle, a Trailer Truck bearing YN6514A did not look out for other vehicles and inched out from Joo Koon Circle. Thus, I collided into the left side wheel of the trailer truck. Upon collision, I fell off my motorbike and landed on my right side, injuring my right leg and shoulder. The said trailer driver then called for ambulance. Soon, ambulance arrived and I was being conveyed. I was being conveyed to Ng Teng Fong General Hospital and was given 05 days of MC. I do not know the damages of my motorbike as it was being towed by the traffic police.

I wish to state that I did not manage to get the other party's particulars as we did not get to converse



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999



Report No. 127

CONTINUATION OF REPORT


Sketch Plan

Informant is not able to provide sketch plan

Exchange Ad

Dear

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
J/
TAN RUI JIE 

Signature Of Informant: 

Signature Of Interpreter:
Not applicable

Date/Time:
22/04/2019 16:23


Officer In Charge Of Case:
TP / GIT /
Insp TAN CHIN YONG
Contact No.: 65476178

Classification Of Case:

Authentication Stamp
NP168



SN 127

































Signature : 

Singapore Police Force

Claim Documents

***WXA312 (591779)**
[YN6514A]
TP
LEOW CHUAN CHIEW
Apr 18 2019 7:00AM
[JA LAN TIONG PTE LTD]
Sincere Lead Automotive

Upload Documents Upload Photos Compose New Letter		View View in Browser		
Assessment Reports		1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/04/19 10:09	Accident Statement <small>From: SC - Reg. No: YN6514A, Claimant: JA LAN TIONG PTE LTD</small>	Load HTM	<input type="checkbox"/>
Photos/Images		3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
2	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
3	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
4	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
5	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
6	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
7	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
8	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
9	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
10	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
11	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
12	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
13	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
14	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
15	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
16	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
17	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
18	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
19	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
20	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
21	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
22	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
23	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
24	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
25	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
26	02/05/19 09:06	General View	Load JPG	<input checked="" type="checkbox"/>
27	23/05/19 08:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
28	23/05/19 08:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
29	23/05/19 08:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
30	23/05/19 08:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
31	23/05/19 08:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
32	23/05/19 08:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
33	23/05/19 08:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	23/05/19 08:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	23/05/19 08:45	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	23/05/19 08:45	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	23/05/19 08:45	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	23/05/19 08:45	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/04/19 10:10	TP Police Rpt	 Load PDF	
2	29/04/19 10:18	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19007570/JCD3E2

Date: 24/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28625376MKC

Claimant Vehicle No: WXA312

Insured Vehicle No: YN6514A

Date of Loss: 18/04/2019

Nature of Claim: TP

Claim No: 591779

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **WXA312**

Make & Model: BAJAJ PULSAR 200 NS, 200cc

Engine No: JLYCJE53732

Reg. Date: 31/03/2019 (Man. Year: 2018)

Chassis No: PMNNS200NJML03913

Colour: Black

Odometer: 548 km

Engine Capacity: 200 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80-17

Rear Tyre Size: 130/70-17

Front Left Side: Nylogrip Zapper 6 mm

Rear Left Side: Nylogrip Zapper 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/04/2019

Date Inspected: 30/04/2019 Inspected At:

Sincere Lead Automotive (Woodlands 3)
38 Woodlands Ind. Park E1 #05-13
Singapore 757710

Estimated Period of Repair: 3.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 May 2019)	
Parts:	N/A	BAJAJ PULSAR 200 NS 200cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WXA312)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >