



Your Ref: S1M030SB

Date: 05th Aug 2021

Our Ref: CS3/ASM21001337/Gtf3e2-1

M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP

36 Robinson Road #12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBR 8262P

INSURED VEHICLE: SH 6828Y

ACCIDENT DATE: 16/01/2021

We thank you for your instruction on 01/07/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBR 8262P from M/s Prudent Adjustors Services.
- b) Singapore Accident Statement and Police Report of Vehicles FBR 8262P and SH 6828Y.
- c) Final Repair Bill of FBR 8262P from M/s Ong Motor Pte Ltd.
- d) Colour damaged vehicle photographs of FBR 8262P.

Pre-Repair Inspection Date : 28/01/2021 at M/s Ong Motor Trading, No. 464 Macpherson Road, Singapore 368182.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBR 8262P
Make & Model	: Yamaha NMAX 155 ABS CVT
Year of Registration	: 2020
Chassis Number	: MH3SG5680LK038836
Engine Capacity	: 155 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.