COMFORTDELGRO

Our J Date	lob Re	_	305475588 01/07/21	ComfortDe		INEERING ortDelGro Engineering Pte Ltd rang Drive Singapore 508969	
FINALIZATION FORM					Fax: 6546 8156		
То	: ;=		LKK	_	Fax:		
Attn : RASUL							
Vehicle Reg No. SH 9937X				Da	ate of Accident	25.06.21	
The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-							
1.	The r	epair job shall bill	to:	NTUC	MIE.	SKQ7782K	
2.	The finalized amount shall be:						
	(a) Spare Parts after List discount						
	(b)	Labour Charges					
	Total for Part-By-Part Repair Cost						
	(c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% Final Lumpsum Repair cost					\$1,150.00 \$1,150.00	
<ul><li>3.</li><li>4.</li><li>5.</li></ul>	Estimated normal period for repairs:  We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days  Thank you for your assistance.  We confirm the estimates and finalized amount						
	Signature : LIM T S		ymp	. Si	gnature :	Rasul	
				, N	ame :	RASUL	
	Tel : 62148398		8	Date ;0		05/07/21	
Fax : 65468156							
For Official Use Only							
	ltem		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
Rental Rate P/Day				YES			
Loss of Income Paid				N			
Survey Fees				(100			
LTA Search Fee     Medical Fees (on behalf of			\$7.49 /\$2.00				
driver, if applicable)							
6 Overrun							
Remarks:							