

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



AUTOMOBILE INSPECTION REPORT						
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21007222/R1vcn2						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	08-07-2021		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMV 3334Y	Veh. Ir	nspected	SH 8670X	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1136607-001	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	29/06/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40 1.7 CRDI	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU087929	Colour		BLUE	
	Odometer	612053	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	DURAT	URN	6 mm	
	L/H Front Tyre	205/60 R16	DURAT	URN	6 mm	
	R/H Rear Tyre	205/60 R16	DURAT	URN	6 mm	
	L/H Rear Tyre	205/60 R16	DURAT	URN	6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	23/06/2021	Inspec	ction Date	29/06/2021	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					