

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

8 SHENTON WAY #24-01 Date: 28/AXA TOWERSINGAPORE 068811 ATTN: ANG YVONNE Code: AS 1. Policy Particulars :- THIRD PARTY CLAIM	MR 7523M
AXA TOWERSINGAPORE 068811 ATTN: ANG YVONNE Code: AS Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SHC 1633G Veh. Inspected SM	MR 7523M
1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SHC 1633G Veh. Inspected SN	MR 7523M
Insured Veh. SHC 1633G Veh. Inspected SM	
Policy No. VFX/P2419138 Coverage (\$) 0.0	00
Claim No. S1M03CUF Excess (\$) 0.0	00
Assign From ANG YVONNE Assign Date 01/	/07/2021
2. Vehicle Particulars & Condition	
Make & Model TOYOTA NOAH (A) c.c 179	97
Engine No. HIDDEN Year of Reg. 203	20
Chassis No. ZWR800419739 Colour ME	ETALLIC BLACK
Odometer 158058 KM Steering IN	ORDER
Brakes IN ORDER Modification ST	TANDARD ALLOY RIM
General GOOD	
3. Conditions of Tyres	
Size Make Ba	alance
R/H Front Tyre 195/65 R15 YOKOHAMA 8 n	mm
L/H Front Tyre 195/65 R15 YOKOHAMA 8 n	mm
R/H Rear Tyre 195/65 R15 YOKOHAMA 8 n	mm
L/H Rear Tyre 195/65 R15 YOKOHAMA 8 n	mm
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.	
DAMAGES SEE DETAILS.	
5. General Information	
Accident Date 29/06/2021 Inspection Date 05/	5/07/2021
Survey held at BLK 5038 ANG MO KIO INS PARK 2 #01-405 S 569541	
Repairer MASSIVE TRADING & AUTO	
5a. Remarks	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days	