



Claim	S1M03CUF
Reference	CS/ASM21007234/Ktce2 
Loss Date	29 June 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	30 Jun 2021 11:15:02 PM
Request Date	1 July 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident

SMR7523M

Vehicle
Registration #

Make

TPVD

Model

TOYOTA

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

- Messages2
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 PRI TP PDF.pdf.pdf	Other	Other	do not reply	
 ASM-LKKInvoice-AC2105272.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	30 July 2021
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	30 July 2021

FAQ English (SG) ▼ Elaine Kuan ▼			E	SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	...	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	30 July 2021
	 LKKPhotosIn6 (1).pdf.pdf		Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	23 July 2021
	 LKKPhotosIn6 (2).pdf.pdf		Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	23 July 2021
	 LKKPhotosIn6.pdf.pdf		Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	23 July 2021
	 AXA Immediate Advice _ TP SMR 7523M.pdf.pdf		Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 July 2021
	 TP GIA.pdf.pdf		Reports & Statement	GIA Report	KUMAR Shailendra	1 July 2021
	 PRI TP EMAIL FROM SOLICITOR.msg.msg		Legal	Others	KUMAR Shailendra	1 July 2021

FAQ English (SG) ▾ Elaine Kuan ▾			E	SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	...	gal	Others	KUMAR Shailendra	1 July 2021
			 SJ04216T000X-SHC1633G.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2