



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JANICE KOH			Ref: CC4/ASM21007237/Ags3q2 Date: 19/11/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XE 4714L	Veh. Inspected	SJK 6063C	
Policy No.	P2385960	Coverage (\$)	0.00	
Claim No.	S1M03CQ6	Excess (\$)	0.00	
Assign From		Assign Date	30/06/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA AXIO	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NZE1416090624	Colour	GOLD	
Odometer	313741 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/55 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/55 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/55 R15	WEST LAKE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/06/2021	Inspection Date	30/06/2021	
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	