

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SMRT AUTOMOTI	VE SERVICES PTE LTD	R	ef:	CS3/SMR21005952/T1uce2-1	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705	Da	ate:	08/07/2021	
			C	ode:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SG 5856C	Veh. Inspected		SMZ 1582P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	BUS/05/21/5013	Excess (\$)		0.00	
	Assign From	KAREN CHAN	Assign Date		01/07/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN BEETLE1.6	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2005	
	Chassis No.	WVWZZZ9CZ6M500445	Colour		WHITE	
	Odometer	119819 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/45 R17	FALKEN		6 mm	
	L/H Front Tyre	225/45 R17	FALKEN		6 mm	
	R/H Rear Tyre	225/45 R17	FALKEN		6 mm	
	L/H Rear Tyre	225/45 R17	FALKEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND UNDERCARRIAGE.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	08/05/2021	Inspection Date		18/05/2021	
	Survey held at	SNG AUTO TRADING				
		60 JALAN LAM HUAT, #05-35, CARROS CENTRE, SINGAPORE 737869				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	12	2 Worl	king Days	