



## Case Details

Case Reference Number :  
TAX/06/21/2063  
Type of Repair : Accident Repair  
Vehicle Registration Number : SHB610J

Company Type : SMRT Taxis Pte Ltd  
Estimation ID : EST-15305-ID  
Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd  
Accident Date and Time : 30/06/2021 07:50 AM  
Vehicle Age(In Months) : -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	de
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	nu
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	nu
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	?
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	?
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	?
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	?
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	?
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	ASU
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	ASU

Total Spare Part Cost 8,753.10

Surveyor Total 518.62

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 7,002.48

Final Sur Total 414.90



SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	Xan
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	Xan
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	Xan
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	Xsu
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	Xsu
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	Xsu
One Time Key In	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.92	Replace	0	0	Not Give	Xsu
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	0	Repair	R
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	0	Repair	R
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE DOOR GLASS	1	1,090.90	1,090.90	25.00	818.18	Replace	0	0	Not Give	Xan
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give	Xan
One Time Key In	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give	Xan

Total Spare Part Cost 8,753.10

Surveyor Total 518.62

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 7,002.48

Final Sur Total 414.90

SMRT Recommendation											Surveyor Approval			
Item Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	0	0	Not Give	Xan
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	0	0	Not Give	Xan
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	17.40	17.40	25.00	13.05	Replace	0	0	Not Give	Xan
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give	Xan
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE TRIM, RH	1	88.30	88.30	25.00	66.22	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE TRIM, UPPER	1	49.60	49.60	25.00	37.20	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE, BAORD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Not Give	Xan
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Give	Xan

Total Spare Part Cost	8,753.10	Surveyor Total	518.62
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	7,002.48	Final Sur Total	414.90



BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give	Xm
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	na
One Time Key In	Main			NAME PLATE (PRUIS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Give	Xm
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	Xm
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give	Xm
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give	Xm
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	Xm
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	Xm
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Not Give	Xm
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give	Xm
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Not Give	Xm
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Not Give	Xm
Total Spare Part Cost									8,753.10	Surveyor Total		518.62		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									7,002.48	Final Sur Total		414.90		

**Labour's Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	400	
<b>Total:</b>			<b>676.00</b>	<b>400.00</b>	

**Spray Cost Detail**


No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	Xan
3	Main	TO RESPRAY REAR PANEL	180.00	100	
4	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	Xan
5	Main	TO RESPRAY TAIL GATE	378.00	200	
6	Main	TO RESPRAY REAR SPOILER	180.00	0	Xan
<b>Total:</b>			<b>1,476.00</b>	<b>500.00</b>	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60	
2	Main	TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0	Xan
3	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	Xan
4	Main	TO REMOVE AND REFIX TAILGATE GLASS	120.00	0	Xan
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	Xan
6	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	Xan
7	Main	TO WASH AND VACUUM	60.00	0	Xan
8	Main	TOWING CHARGE	56.00	0	Xan
9	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
<b>Total:</b>			<b>1,072.88</b>	<b>356.88</b>	

**Summary**

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	7,002.48	414.90
Total Labour Cost	676.00	400.00
Total Spray Painting	1,476.00	500.00
Other	1,072.88	356.88

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Overall Total	10,227.36	1,671.78
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	10,250.00	1,650.00
Surveyor Approved Amount		1,650.00
No of Repair Days*	6	4
Remarks	-	lump sum repair / after repair photo.
Surveyor Name		Rasul
Signature		
		<input type="button" value="Save"/> <input type="button" value="Clear"/>
Survey Date	01/07/2021	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	01/07/2021 14:13 (SGT)
Date of Accident	30/06/2021 15:50 (SGT)
Exact Location of Accident	Sims Ave, Singapore
Additional Location Information	SIMS AVENUE TOWARDS GEYLANG SERAI MARKET
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB610J
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	SMRT TAXIS PTE LTD
-	1XXXXX369K
Email Address	AUTO-SVC-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

## VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

## INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-21097466MFSH
Cover Note Number	-

## DRIVER

Name of Driver	FOO JEE SENG
NRIC No	SXXXX266Z



Date of Birth ..... 27/09/1960  
 Occupation ..... Outdoor  
 Date of Driving Pass ..... 06/10/1982  
 Driving experience ..... 38 YEARS AND 8 MONTHS  
 Gender ..... Male  
 Mobile Number ..... (Phone) +65-68662671  
 Home Phone Number ..... -  
 Email Address ..... AUTO-ARC-TARC@SMRT.COM.SG  
 Address ..... 11  
 Address complement ..... -  
 Postcode ..... -  
 Is the driver the policyholder? ..... -  
 If No, Relationship of the Driver with the Insured ..... No  
 Does Driver Own Other Vehicles? ..... Hirer  
 Vehicle Registration Number of Other Vehicle Owned by Driver ..... No  
 Insurance Company of Other Vehicle Owned by Driver ..... -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident ..... Collision - Head to Rear  
 Weather Conditions ..... Clear  
 Road Surface ..... Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? ..... No  
 Number of vehicles involved in the accident ..... 2  
 Was anybody injured in the Accident? ..... No  
 Was any injured conveyed to hospital by ambulance? ..... -  
 Was any other vehicle or property damaged? ..... Yes  
 Number of Passengers (Including Driver) ..... 5  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? ..... No

PASSENGER 1

Name ..... UNKNOWN  
 Gender ..... Female

PASSENGER 2

Name ..... UNKNOWN  
 Gender ..... Female

PASSENGER 3

Name ..... UNKNOWN  
 Gender ..... Female

PASSENGER 4

Name ..... UNKNOWN  
 Gender ..... Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? ..... No  
 Was notice of intended Prosecution given? ..... No  
 If yes, against whom? ..... -

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG SIMS AVENUE TOWARDS GEYLANG SERAI MARKET WITH 4 PASSENGERS (FEMALE MALAY) ON BOARD AND SLOWED DOWN TO A STOP AS THE TRAFFIC LIGHT TURNED RED. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SJH5497G HAD COLLIDED ONTO THE REAR OF MY TAXI.

ATTACHMENT(S)

Accident photos available for attachment? ..... Yes  
 Was there any video captured by Car Camera? ..... No  
 Was there any audio recorded? ..... No

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number ..... SJH5497G  
 Vehicle Manufacturer ..... -  
 Vehicle Model ..... -  
 Vehicle Variant ..... -  
 Vehicle Colour ..... -  
 Vehicle Category ..... Private car  
 Name of Driver ..... -  
 Contact Number ..... -  
 Address ..... -  
 Address complement ..... -  
 Postcode ..... -  
 Insurance Company Name ..... -  
 Nature Of Damage ..... -  
 Details of property damaged in accident ..... -  
 No. Of Passenger (Including Driver) ..... -

Bal.  
 AC  
 /  
 Rep  
 m:  
 EV





**SKETCH PLAN**

**IMPORTANT NOTICE**

- 1 Please report **correctly** the details of the accident to speed up the claims process.
- 2 This Form must be **completed by the Policyholder and/or the Authorised Driver**.
- 3 Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 **Any false reporting may be referred to the Police for investigation**
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Sketch Plan

*[Signature]*  
1, July 2021 11.35am  
Driver's Signature (if driver is not the policyholder) / Date & Time

*[Signature]* 1/7/2021  
Witnessed by Reporting Centre Personnel



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHB610J
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jul 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1411851
Chassis No.:	JTDKN36U305749710
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	17 Sep 2014
First Registration Date:	17 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Sep 2022
PARF Rebate Amount:	\$5,257.00
COE Expiry Date:	16 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$7,640.00
<b>Total Rebate Amount:</b>	<b>\$12,897.00</b>

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Jul 2021

OK