



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21007315/Kuf3n2	
			Date: 07/07/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 5678G	Veh. Inspected	SMY 6129M	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/06/21/2043/MA	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	05/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	KNAF3416MM5101228	Colour	METALLIC GREY	
Odometer	950 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	KUMHO	9 mm	
L/H Front Tyre	205/55 R16	KUMHO	9 mm	
R/H Rear Tyre	205/55 R16	KUMHO	9 mm	
L/H Rear Tyre	205/55 R16	KUMHO	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/06/2021	Inspection Date	05/07/2021	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	