

ASS. REC. BY:

REF: CS/

Smo/ 21007316/Kqf3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBJ 8641X

at Workshop m/s

of

Insured: SKQ 4084L

Policy No.

Claims No. CMTD2101983/AGC

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

GBJ 8641X Yr Regn: 09, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV200 c.c. 1597

Colour:

Grey A/C: Insured / Std / NI / NA

Sp. Reading

37652 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VN 20 137132

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: _____

R: 165/80R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Toyo

Front

Rear

R/Bal.

6 mm

R/Bal. 6 mm

L/Bal.

6 mm

L/Bal. 6 mm

D.O.A.

1/7/21

D.O.I. 5/7/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

NIS for body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/7/2021 @ 10.03am Revise to Grace via email.

Kenneth finalised LS \$7900, 8 days. (Red \$11980.26, 60%)

Date/Time, File Pass to?

☐ : Prell. Report

1/25/03 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format: TP

Lump Sum H.B. (\$) 7900

Not Authorized
 Penny Bepain
 8 days



Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 100B,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

05/07/2021

SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623.

Attention :- XA018

Page # :- 1
 Veh # :- GBJ8641X
 Veh Model :- NISSAN NV200
 Estimate# :- CK422027
 Claim # :-
 ACC. Date :- 01/07/21
 Terms :- C.O.D Days
 Remarks :-

| No. | Description | Qty | U.Price | Amounts S\$ |
|-----|-------------|-----|---------|-------------|
|-----|-------------|-----|---------|-------------|

NET ITEMS :

| | | | | | | |
|-----|------------------------------------|----|----|----------|----------|---|
| 1. | FRONT BUMPER | 1 | PC | 655.20 | 655.20 | ✓ |
| 2. | FRONT BUMPER SIDE LH | 1 | PC | 405.30 | 405.30 | ✓ |
| 3. | FRONT BUMPER RETAINER LH | 1 | PC | 54.30 | 54.30 | ✓ |
| 4. | FRONT BUMPER CLIPS | 10 | PC | 4.40 | 44.00 | ✓ |
| 5. | FRONT HEAD LAMP LH | 1 | PC | 537.90 | 537.90 | ✓ |
| 6. | FRONT HEAD LAMP CLIPS | 1 | PC | 4.50 | 4.50 | ✓ |
| 7. | FRONT FENDER LH | 1 | PC | 555.20 | 555.20 | ✓ |
| 8. | FRONT FENDER COLWING LH | 1 | PC | 154.20 | 154.20 | ✓ |
| 9. | FRONT FENDER COLWING CLIPS | 10 | PC | 4.40 | 44.00 | ✓ |
| 10. | FRONT FENDER EMBLEM "NISMO" | 1 | PC | 69.30 | 69.30 | ✓ |
| 11. | FRONT FENDER SIGNAL | 1 | PC | 54.60 | 54.60 | ✓ |
| 12. | FRONT DOOR LH | 1 | PC | 1,287.50 | 1,287.50 | ✓ |
| 13. | FRONT DOOR HINGE LH | 2 | PC | 64.80 | 129.60 | ✓ |
| 14. | FRONT DOOR PILLAR LH | 1 | PC | 7,229.70 | 7,229.70 | ✓ |
| 15. | FRONT DOOR BLACK TAPE LH | 1 | PC | 58.60 | 58.60 | ✓ |
| 16. | FRONT DOOR REGULATOR LH | 1 | PC | 387.50 | 387.50 | ✓ |
| 17. | FRONT DOOR WIRE LH | 1 | PC | 382.40 | 382.40 | ✓ |
| 18. | FRONT DOOR LOCK LH | 1 | PC | 172.30 | 172.30 | ✓ |
| 19. | FRONT DOOR RUBBER LH | 1 | PC | 138.60 | 138.60 | ✓ |
| 20. | ROCKER PANEL LH | 1 | PC | 1,353.60 | 1,353.60 | ✓ |
| 21. | FRONT WHEEL COVER LH | 1 | PC | 145.90 | 145.90 | ✓ |
| 22. | FRONT WHEEL RIM LH | 1 | PC | 207.10 | 207.10 | ✓ |
| 23. | FRONT LOWER ARM RH | 1 | PC | 299.60 | 299.60 | ✓ |
| 24. | FRONT LOWER ARM BRACKET | 1 | PC | 125.10 | 125.10 | ✓ |
| 25. | FRONT CROSS MEMBER | 1 | PC | 679.20 | 679.20 | ✓ |
| 26. | FRONT SHOCK ABSORBER | 1 | PC | 258.60 | 258.60 | ✓ |
| 27. | FRONT STEERING RACK & PINION | 1 | PC | 1,779.60 | 1,779.60 | ✓ |
| 28. | FRONT DRIVER SHAFT LH - TO CONFIRM | 1 | PC | | | |
| 29. | FRONT ENGINE MOUNTING - TO CONFIRM | 1 | PC | | | |
| 30. | CENTER PILLAR LH - TO REPAIR | 2 | PC | | | |
| 31. | REAR DOOR LH - TO REPAIR | 1 | PC | | | |

NET TOTAL S\$

10% DISCOUNT S\$

17,213.40

-1,721.34

15,492.06

SPECIAL NET ITEMS :

| | | | | | | |
|----|---------------------|---|----|--------|--------|---|
| 1. | FRONT DOOR STICKER | 1 | PC | 50.00 | 50.00 | ✓ |
| 2. | FRONT TYRE LH | 1 | PC | 180.00 | 180.00 | ✓ |
| 3. | FRONT WHEEL BEARING | 1 | PC | 345.80 | 345.80 | ✓ |
| 4. | FRONT KNUCKLE ARM | 1 | PC | 372.40 | 372.40 | ✓ |

SPECIAL NET TOTAL S\$

948.20

LABOUR :

TOWING CHARGE

80.00

TO CUT & WELD FRONT DOOR PILLAR LH, ROCKER
 PANEL LH, CENTRE PILLAR LH, TO REPAIR FRONT
 FLOOR PANEL LH, REAR DOOR LH, TO REMOVE &

Estimate

05/07/2021

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1 141421
Veh # :- GBJ8641X
Veh Model :- NISSAN NV200
Estimate# :- CK422027
Claim # :-
ACC. Date :- 01/07/21
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

| No. | Description | Qty | U.Price | Amounts S\$ |
|-----|--|-----|---------|-------------|
| | REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS | | | 800 |
| | TO SPRAY AFFECTED AREAS | | | 1,400.00 |
| | TO REMOVE & REFIX DOOR MECHANISM,CHECK & TEST POWER WINDOW & CENTRE LOCKING SYSTEM | | | 1,200.00 |
| | TO REMOVE & REFIX DASH BOARD, GLOVE BOX AND OTHER ATTACHMENT PARTS | | | 60.00 ✓ |
| | TO REMOVE & REFIX CUSHION, CARPET AND OTHER ATTACHMENT PARTS | | | 180.00 X |
| | TO REMOVE & REFIX FRONT SUSPENSION, LOWER ARM, SHOCK ABSORBER AND OTHER ATTACHMENT PARTS | | | 80.00 X |
| | TO CHECK WHEEL ALIGNMENT | | | 180.00 ? |
| | TO RUST PROOF AFFECTED AREAS | | | 100.00 |
| | TO REMOVE & REFIX WIRE HARDNESS, CHECK & TEST WERE NECESSARY | | | 80.00 ✓ |
| | LABOUR TOTAL S\$ | | | 80.00 X |
| | | | | 3,440.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 19,880.26

GST @ 7 % 1,391.62

AMOUNT DUE S\$ 21,271.88

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTES

1. Please report straight after details of the accident to speed up the claims process.
2. This Form is to be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false information may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 02/07/2021 14:55 (SGT)
Date of Accident 01/07/2021 19:29 (SGT)
Exact Location of Accident Singapore
Additional Location Information HUNDRED TREES CONDO
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBJ8641X

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner KENDORI MARINE ENGINEERING PTE. LTD.
Company Reg No 2XXXXX011C
Email Address LOUIS.KENDORMARINE@HOTMAIL.COM
Mobile Phone No (Phone) +65-93801068
Alternative Phone No +65-93801068

VEHICLE PARTICULARS

Manufacturer Nissan
Model Nv200
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Auto
CC 1597

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5112756818-01
Cover Note Number -

DRIVER

Name of Driver LOUIS TAN YU WEI
NRIC No SXXXX228G

| | |
|--|------------------------------------|
| Date Of Birth | 10/11/1993 |
| Occupation | Indoor |
| Date Of Driving Pass | 24/04/2012 |
| Driving experience | 9 YEARS AND 3 MONTHS |
| Gender | Male |
| Mobile Number | (Phone) +65-93801068 |
| Alt. Phone Number | - |
| Email Address | LOUIS.KENDORMARINE@HOTMAIL.COM |
| Address | BLK 442A BUKIT BATOK WEST AVENUE 8 |
| Address complement | #04-871 |
| Postcode | 651442 |
| Is the driver the policyholder? | No |
| If No, Relationship of the Driver with the Insured | Employee |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|------------------------|
| Type of Accident | Collision - Roundabout |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 2 |
| Was anybody injured in the Accident? | Yes |
| Was any injured conveyed to hospital by ambulance? | Yes |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 1 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

REFER TO THE SKETCH PLAN

ATTACHMENT(S)

| | |
|---|---------------------------------|
| Are accident photos available for attachment? | No |
| Was there any video captured by Car Camera? | Yes |
| Reasons for not uploading a video of the accident | WILL SEND TO INSURANCE DIRECTLY |
| Was there any audio recorded? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKQ4084L |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Private car |
| Name of Driver | DAIKUHARA SEIJI |
| Passport No/FIN | GXXXX697X |
| Contact Number | (Phone) +65-97227442 |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;


(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time
02 July 2021 | 1350 HRS


Driver's Signature (if driver is not the policyholder) / Date & Time
02 July 2021 | 1350 HRS


Witnessed by Reporting Centre Personnel

Sketch Plan

