



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21007316/Kqf3n2	
			Date: 01/04/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKQ 4084L	Veh. Inspected	GBJ 8641X
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2101983/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	05/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV200 (A)	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	VM20137132	Colour	GREY
	Odometer	37052 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	165/80 R14	TOYO	6 mm
	L/H Front Tyre	165/80 R14	TOYO	6 mm
	R/H Rear Tyre	165/80 R14	TOYO	6 mm
	L/H Rear Tyre	165/80 R14	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/07/2021	Inspection Date	05/07/2021
	Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	