Surveyor:

REF: CS/FCI21007322/Dqf3

Special Instruction:

L/SUM : $ 75,900.00

Third Parties:

Claimant:

Surveyor: SMRT

Workshop: C.S.ONG AUTO PTE LTD

ASSIGNMENT (Office)

From (Person): ESTHER LIM of FCI Date/Time: 2/7/2021 6:16 PM

Estimated Cost: Bill to:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SKW 6026K Insured: SHB 834E

at Workshop m/s C.S.ONG AUTO PTE LTD Tel: 6484 1933

of Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint, 568047 Ang Mo Kio

Policy No: Claim No: D21000924MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 23/03/2021

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle **IN / OUT**

Date/Time: **Confirmed with** **Final Fig** , days (Red $ / %; Original 19 days)

Date/Time: 16/07/21 **Submit ~~Final Fig~~** LS $55000 , 16 days (Red $20900 / 28 %; Original 19 days)

Date/Time	Action/Instruction
	SKW 6026K- X
	SHB 834E-NS/INC17014266/Sqbe2 DOA : 19/07/2017

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

65x15=975

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	170+975
Transport	50
Photos	78
Others	
Total	1273

1) Date/Time 21/07/21 File Pass to Typist 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to