

(06/11/13) Wef

ASS. REC. BY: *Sam*

REF:

CS/CTI 21007324/Rinc

7486

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *SOK 7201K*at Workshop m/s *Volkswagen*of *247, Alexander Rd*Insured: *CTI SJW 2861D*Policy No. *DMHCSNW00002152101*Claims No. *SNM21D203691/C02*

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition) *2pm*

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *44K*

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

*SOK 7201K*Yr Regn: *2012 / NOV*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

*Volkswagen Sharan 2.0 TSI c.c 1984*

Colour:

*Brown*

A/C: Insured / Std / NI / NA

Sp. Reading:

*63349*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*WVW2227N2DVo12310*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *Inorder* / Jammed / Leaked / Burnt orBrake: *Inorder* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

*225/452R18*

R:

BS / DUN / EXNOVA / GY / FS / LIZA *MIC* / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

*6*

mm

R/Bal.

*6*

mm

L/Bal.

*6*

mm

L/Bal.

*6*

mm

D.O.A.

*01/07/21*

D.O.I.

*07/07/21*

Survey held at

*Volkswagen*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*FRT 6/5*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*Repair limit - 8K*

8/7/2021 @ 11.08am Revise to CTI via Merimen.

16/7/2021 Confirmed final fig P/P \$7127.16, 4 repair days via email.

(RED \$5649.29; 44%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 16/7 TYPIST

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) : S + RS, SI

☐

: Interview (\$

) : Photos

☐

: Tech. Invs (\$

) : Others

☐

: Weekend (\$

)

Report Format : TP

Lump Sum / I.B.I: (\$ 7127.16)

TOTAL



## VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

1/2

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Ms.  
CORDELIA  
LEE  
261 RIVER VALLEY ROAD  
#10-28  
Singapore 238307

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor

02-07-2021  
5211001170  
200208384E  
30001  
2021024705/ 1  
02-07-2021  
SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SDK7201K	7N14H3	30-11-2012	VWVZZZ7NZDV012310	Sharan succ. HL 147 TSID6F	61,175

Repair Limit:

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
7N0831056AF	Door RHF	1	pcs.	2,281.09	#1	2,281.09	2,440.77
7N0837701C	Door Seal Outer RHF	1	pcs.	361.35	#1	361.35	386.64
D 378500A2	Sound Absorber Laminated RHF	1	pcs.	43.65	#1	43.65	46.71
7N0821022B	Fender RHF	1	pcs.	807.29	#1	807.29	863.80
7N0821136A	Cross Support RHF FENDER BRACKET	1	pcs.	49.27	#1	49.27	52.72
D 314D36M2	Long-Life Underseal	1	pcs.	87.64	#1	87.64	93.77
7N2857508AC9B9	Rear View Mirror Housing RH	1	pcs.	815.87	#1	815.87	872.98
5N0857538 GRU	Mirror Cap Primed RH	1	pcs.	137.26	#1	137.26	146.87
5N0857522C	Mirror Glass RH	1	pcs.	207.82	#1	207.82	222.37
	LABOUR	4	pcs.	840.00	#1	3,360.00	3,595.20
	Spray Painting	4	pcs.	800.00	#1	3,200.00	3,424.00
	Spray Painting Wing Cover	1	pcs.	280.00	#1	280.00	299.60
	CHINA TAIPING DIRECT SETTLEMENT DOA: 2/7/2021 TP VEH: SJW2861D SURVEY BY:						

Quotation valid till 09-07-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	11,631.24	7%	867.39	12,391.24	13,258.63
Total	760.00	11,631.24		867.39	12,391.24	13,258.63

Customer

Asul  
HP 90010060  
4 days

07/07/21 @ 14/10 Service Advisor

Resumy before paint

# VOLKSWAGEN CENTRE SINGAPORE

7 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

2/2

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Ms.  
CORDELIA  
LEE  
261 RIVER VALLEY ROAD  
#10-28  
Singapore 238307

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor

02-07-2021  
5211001170  
200208384E  
30001  
2021024705/ 1  
02-07-2021  
SHU SHI TANG

License plate  
SDK7201K

Model code  
7N14H3

First registration  
30-11-2012

VIN  
WVWZZZ7NZDV012310

Model  
Sharan succ. HL 147 TSID6F

Mileage  
61,175

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	02/07/2021 08:41 (SGT)
Date of Accident	01/07/2021 14:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	FUNAN CENTRE DROP OFF POINT
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDK7201K
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CORDELIA LEE
NRIC No	SXXXX748F
Email Address	leedelia@hotmail.com
Mobile Phone No	(Phone) +65-96269368
Alternative Phone No	+65-96269368

#### VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Sharan
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

#### INSURANCE COMPANY

Name of Insurance Company	FWD Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	PNPV2019-00017481-01
Cover Note Number	-

#### DRIVER

Name of Driver	TAN ADRIAN YING CHUAN
NRIC No	SXXXX747H



Date of Birth	24/08/1972
Location	Indoor
Date of Driving Pass	21/10/2003
Driving experience	17 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96607988
Alt. Phone Number	-
Email Address	leedelia@hotmail.com
Address	261 RIVER VALLEY ROAD
Address complement	#10-28
Postcode	238307
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW2861D
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	-
Contact Number	-
Address	-
Address complement	-



Code ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
Name Of Passenger (Including Driver) ..... -



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:




Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SKETCH PLAN




## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was driving along North Bridge Road on 1/7/21 at around 14:15hrs and as I was passing Funan Mall a BLUE TOYOTA AC TIS SJW2861D was coming out of Funan Mall drop off point and side swiped my car SDC 201K. It was sunny and road conditions were light.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



## Require PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

748F

## Vehicle Details

Vehicle No.:

SDK7201K

Vehicle to be Exported:

Yes

Intended Deregistration Date:

05 Jul 2021

Vehicle Make:

VOLKSWAGEN

Vehicle Model:

SHARAN 2.0 TSI AT 7N14H3

Primary Colour:

Brown

Manufacturing Year:

2012

Engine No.:

CCZ310362

Chassis No.:

WVWZZZ7NZDV012310

Maximum Power Output:

147.0 kW (197 bhp)

Open Market Value:

\$40,732.00

Original Registration Date:

30 Nov 2012

First Registration Date:

30 Nov 2012

Transfer Count:

0

Actual ARF Paid:

\$40,732.00

## Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

29 Nov 2022

PARF Rebate Amount:

\$22,402.00

## Intended COE Rebate Details

COE Expiry Date:

29 Nov 2022

COE Category:

B - Car (1601cc &amp; above)

COE Period(Years):

10

QP Paid:

\$90,501.00

COE Rebate Amount:

\$12,670.00

Total Rebate Amount:

\$35,072.00

The information contained herein is correct as at 05 Jul 2021

OK



# Volkswagen Sharan 2.0A TSI Sunroof

## Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$53,800****Depreciation** ⓘ

\$14,650 /yr

[View models with similar depre](#)**Reg Date**

17-Jul-2013

(2yrs 8days COE left)

**Mileage**

70,000 km (8.8k /yr)

**Manufactured** ⓘ

2013

**Road Tax** ⓘ

\$1,194 /yr

**Transmission**

Auto

**Dereg Value** ⓘ

\$42,611 as of today (change)

**OMV** ⓘ

\$40,241

**COE** ⓘ

\$67,304

**ARF** ⓘ

\$48,338

**Engine Cap**

1,984 cc

**Power**

147.0 kW (197 bhp)

**Curb Weight** ⓘ

1,790 kg

**No. of Owners** ⓘ

1

**Type of Vehicle**

MPV