

ASS. REC. BY:

REF:

GRB/ 21007332/KB

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 31.3% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKY 1036A Yr Regn: 0615Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy ALFA c.c. 1598Colour: n. Silver A/C: Insured / Std / NI / NASp. Reading: 91332 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR053REH104535799Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD A/Rlm orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 25/1/21D.O.I. 28/7/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/9 @ 1694-12 Continued

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	523A
Vehicle Details	
Vehicle No.:	SKU1036A
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jan 2021
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	12RX521184
Chassis No.:	MR053REH104535799
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	30 Jun 2015
First Registration Date:	30 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$14,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2025
PARF Rebate Amount:	\$10,212.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,000.00
COE Rebate Amount:	\$26,992.00
Total Rebate Amount:	\$37,204.00

The information contained herein is correct as at 26 Jan 2021

OK



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 31647

Date : 29-Jan-2021

PAGE : 1

Vehicle Insured : SLQ 8757 R
Accident Date : 25-Jan-2021

Our Ref : 021005 (III) / QUEK

NG CHENG CHENG (MS)
Singapore

NOT Notarised
1.B1

81694.12

ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS 1.6L CVT (2015) SKU1036A

1 pc rear bumper		486.50	X
1 pc n/s rear bumper side retainer		120.00	X
8 pcs rear bumper clips	@ S\$ 5.00	40.00	X
1 pc n/s rear fender inner shield		52.80	X
4 pcs n/s rear fender inner shield clips	@ S\$ 5.00	20.00	X
1 pc n/s rear sport rim (original)	<i>1645.50</i>	<i>1,645.50</i>	✓
1 pc n/s rear wheel hub		670.00	X
1 pc n/s rear wheel hub bearing		200.00	X
1 pc n/s rear shock absorber			
		3,234.80	
	Less 25% :	-808.70	
		2,426.10	

180.00 sn X

1 pc n/s rear tyre

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

450.00 1801

To dismantle and check rear under-carriage. To replace affected portions.

180.00 X

To conduct front wheel alignment test.

80.00 601

To putty and respray on affected portions.

450.00 2201

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total : S\$ 3,766.10

Singapore Dollars Three Thousand Seven Hundred and Sixty Six and Cents Ten Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

Acknowledged by Repairer

Signature:

Date: