

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM21007340/Ars3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	10/12/2021	
	ATTN: YVONNE			Code:	ASM	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SH 8847D	Veh. Inspected	t	SJL 8807E	
	Policy No.	P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03D34	Excess (\$)		0.00	
	Assign From		Assign Date		05/07/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA ALTIS	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	MR053ZEE106134236	Colour		BLUE	
	Odometer	138555 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	CHAMPIRO		6 mm	
	L/H Front Tyre	195/65 R15	CHAMPIRO		6 mm	
	R/H Rear Tyre	195/65 R15	CHAMPIRO		6 mm	
	L/H Rear Tyre	195/65 R15	CHAMPIRO		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/07/2021	Inspection Dat	te	06/07/2021	
	Survey held at	MG SOLUTION PTE LTD				
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	STIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				