

(08/11/13) wef

ASS. REC. BY:

REF:

CC3/A1421007356/Rim3

022B

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFE 821A

at Workshop m/s VOLKSWAGEN

of 247, ALEXANDRA RD

Insured: A14

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

84k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFE 821A

Yr Regn: 2019 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLKSWAGEN GOLF 1.4 TSI c.c. 1395

Colour:

BLU

A/C: Insured / Std / NI / NA

Sp. Reading

44618

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW222ANZKWO93327

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

03/07/21

D.O.I.

07/07/21

Survey held at

VOLKSWAGEN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 48k

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

1/2

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor

05-07-2021  
5211043621  
30001  
2021025142/ 1  
05-07-2021  
PEARLYN CHEONG

Mr  
LIM  
WEE BIN  
21 JALAN SEMPADAN  
#04-14  
Singapore 457398

A16-

License plate	Model code	First registration	VIN	Model	Mileage
SFE821A	BQ13HZ	15-03-2019	WWWZZZAUZKW093327	Golf 1.4 CLBM 92 TSI D7F	212

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
5G0807217FNGRU	Cover For Bumper Primed	1	pcs.	1,313.60	#1	1,313.60	1,405.55
5G0807050B	Guide Piece	1	pcs.	22.75	#1	22.75	24.34
5G0807248G	Foam Insert	1	pcs.	45.29	#1	45.29	48.46
5G0807109AL	Impact Beam	1	pcs.	683.62	#1	683.62	731.47
5G0805915J 9B9	Retainer For Spoiler Sati	1	pcs.	202.62	#1	202.62	216.80
5G0919494G	Sensor Bracket	1	pcs.	13.20	#1	13.20	14.12
5G0919493J	Sensor Bracket	2	pcs.	12.71	#1	25.42	27.20
5G0919493L	Sensor Bracket	1	pcs.	13.20	#1	13.20	14.12
D 822150A1	Bonding Agent For Plastic	1	pcs.	65.18	#1	65.18	69.74
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	81.16	#1	81.16	86.84
5G0854662F RYP	Cooling Air Grill Satin B	1	pcs.	105.90	#1	105.90	113.31
5G0853212H 9B9	Cover Part For Bumper Sat	1	pcs.	36.47	#1	36.47	39.02
5G0853666L 9B9	Cooling Air Grill Satin B	1	pcs.	80.01	#1	80.01	85.61
	LABOUR	4	pcs.	840.00	#1	3,360.00	3,595.20
	LABOUR	4	pcs.	840.00	#1	3,360.00	3,595.20
	Spray Painting	4	pcs.	800.00	#1	3,200.00	3,424.00

Quotation valid till 12-07-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	12,608.42	7%	935.79	13,368.42	14,304.21
Total	760.00	12,608.42		935.79	13,368.42	14,304.21

Customer

Service Advisor

Rasul  
Hp 90010068  
3 days  
07/07/21 @ 1500  
Reay before put

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Mr  
LIM  
WEE BIN  
21 JALAN SEMPADAN  
#04-14  
Singapore 457398

Page

2/2

Document no.	
Document date	05-07-2021
Customer no.	5211043621
Customer GST-ID	
Dealer	30001
Job order number	2021025142/ 1
Job order date	05-07-2021
Service Advisor	PEARLYN CHEONG

License plate  
SFE821A

Model code  
BQ13HZ

First registration  
15-03-2019

VIN  
WWWZZZAUZKW093327

Model  
Golf 1.4 CLBM 92 TSI D7F

Mileage  
212

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



NTUC vs AIG  
Directly

SN0721740001 / NTUC Income Insurance Co-operative Ltd  
ENTRY DATE & TIME: 04/07/2021 09:38 (SGT)  
SUBMITTED BY: Muammar Gaddafi Bin Marzuki  
VERSION: 1 (04/07/2021 09:38 (SGT))

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 04/07/2021 09:38 (SGT)  
Date of Accident ..... 03/07/2021 20:50 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... BEDOK MALL CARPARK BEFORE ENTRANCE GANTRY  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SFE821A

#### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... LIM WEE BIN  
NRIC No ..... S1510022B  
Email Address ..... WEEBINL@YAHOO.COM.SG  
Mobile Phone No ..... (Phone) +65-96250970  
Alternative Phone No ..... +65-96250970

#### VEHICLE PARTICULARS

Manufacturer ..... Volkswagen  
Model ..... Golf  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1400

#### INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 5108154217-02  
Cover Note Number ..... -

#### DRIVER

Name of Driver ..... JEREMIAH LIM KIAN LIP  
NRIC No ..... T0044433I



Date Of Birth .....	06/12/2000
Occupation .....	Indoor
Date Of Driving Pass .....	06/03/2019
Driving experience .....	2 YEARS AND 4 MONTHS
Gender .....	Male
Mobile Number .....	(Phone) +65-96558720
Alt. Phone Number .....	-
Email Address .....	JERELIMAL@YAHOO.COM.SG
Address .....	21 JALAN SEMPADAN #04-14
Address complement .....	-
Postcode .....	457398
Is the driver the policyholder? .....	No
If No, Relationship of the Driver with the Insured .....	Child
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Collision - Head to Rear
Weather Conditions .....	Raining
Road Surface .....	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	2
Was anybody injured in the Accident? .....	No
Was any injured conveyed to hospital by ambulance? .....	-
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No

#### PASSENGER 1

Name .....	ZACK NG
Gender .....	Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	No
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	Yes
Reasons for not uploading a video of the accident .....	ADVISE OI TO SUBMIT TO MOTORVIDEO@INCOME.COM.SG
Was there any audio recorded? .....	Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	SGB3912E
Vehicle Manufacturer .....	Volvo
Vehicle Model .....	V70
Vehicle Variant .....	-
Vehicle Colour .....	-

Vehicle Category .....	Private car
Name of Driver .....	THERESE ANNE MARIE HOWARD
NRIC No .....	S9801485C
Contact Number .....	(Phone) +65-98769055
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	-
Nature Of Damage .....	-
Details of property damaged in accident .....	-
No. Of Passenger (Including Driver) .....	1



**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name: 6800861  
NRIC/FIN No.: J993341



SKETCH PLAN

BECK MALL  
CARPARK ENTRANCE

A - STE 811A  
B - SGB 3911E



BECK MALL  
DROP OFF  
POINT

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS AT BECK MALL CARPARK THE RIGHT TURN BEFORE THE GATEWAY. I WAS STATIONARILY <sup>2</sup> WAITING FOR THE  
CAR IN FRONT OF ME TO TURN. THE CAR IN FRONT OF ME REVERSED TO BACK UP OF THE RIGHT TURN. I HONKED THE  
CAR BUT IT COLLIDED INTO ME

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: GHOSEH  
NRIC/FIN No.: J943841



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	022B
Vehicle No.:	SFE821A
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jul 2021
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI CL
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	CZC999337
Chassis No.:	WWWZZZAUZKW093327
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,156.00
Original Registration Date:	15 Mar 2019
First Registration Date:	15 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$20,219.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Mar 2029
PARF Rebate Amount:	\$15,164.00
COE Expiry Date:	14 Mar 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,309.00
COE Rebate Amount:	\$20,212.00
Total Rebate Amount:	\$35,376.00

The information contained herein is correct as at 08 Jul 2021

OK



# Volkswagen Golf 1.4A TSI Comfortline

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**HTS**motor

Established Since 1989

**Price****\$85,777****Depreciation** ?

\$9,720 /yr

[View models with similar depre.](#)**Reg Date**

30-Apr-2019

(7yrs 9mths 21days COE left)

**Mileage**

37,000 km (16.9k /yr)

**Manufactured** ?

2019

**Road Tax** ?

\$624 /yr

**Transmission**

Auto

**Dereg Value** ?

\$40,717 as of today (change)

**OMV** ?

\$19,702

**COE** ?

\$33,199

**ARF** ?

\$19,702

**Engine Cap**

1,395 cc

**Power**

92.0 kW (123 bhp)

**Curb Weight** ?

1,270 kg

**No. of Owners** ?

1