

ASS. REC. BY:

Tanjil

REF:

CC 4/11/92 (207389/TIG 93)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMJ/422C Yr Regn: 299 FebType: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante c.c. 1591Colour: white A/C: Insured / Std / NI / NASp. Reading: 15508 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHP841CMK486641Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 6/7/21 05pmSurvey held at Primer AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.S. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

6-Jul-21

ESTIMATE REPAIR BILL FOR HYUNDAI AVANTE REGN NO: SMJ 1422 C

1 pc	Rear bumper <i>ana</i>	\$	-
1 pc	Rear bumper reinforcement ?	\$	-
1 pc	Rear bumper n/s side bracket ?	\$	-
1 pc	Rear bumper n/s stay X	\$	-
1 pc	Rear bumper lower cover <i>ana</i>	\$	-
1 pc	Rear bumper n/s reflector <i>ana</i>	\$	-
1 pc	LH tail lamp X	\$	-
1 pc	Rear n/s air extractor	\$	-
		\$	-
		\$	-
		Less 20%	

S/NETT

1 set	Rear bumper clips	\$	48.00 <i>3000</i>
1 set	Reverse sensor	\$	280.00 <i>2000</i>
Sundry		\$	50.00 X
To check wiring		\$	50.00 <i>30</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, rear n/s fender etc		\$	1,000.00 <i>200</i>
To putty and spray painting on the rear bumper, rear bumper lower cover, end panel, rear n/s fender		\$	1,000.00 <i>200.</i>
To apply rustproofing on the repaired and replaced panels.		\$	150.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

Taufik 97415249
wp' 6/7/21 05pm 02days
P/p Resurvey before permit

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: S2600725I
Owner ID Type: Singapore NRIC
Owner Name: CHENG LAI YIN
Registered Address: 105 TANAH MERAH KECHIL AVENUE SINGAPORE 465680
Mailing Address: -
Birth Date: 08 Jul 1967

Vehicle Particulars

Vehicle No.: SMJ1422C
Previous Vehicle No.: -
Effective Date of Ownership: 25 Feb 2019
Original Regn Date: 25 Feb 2019
Registration Date: 25 Feb 2019
Year of Manufacture: 2019
Vehicle Type: Passenger Motor Car
Vehicle Scheme: -
Vehicle Attachment 1: No Attachment
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: HYUNDAI
Vehicle Model: AD AVANTE 1.6 GLS (A) S
Primary Colour: White
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: KMHD841CMKU866441
Engine No.: G4FGKU094990
Engine Capacity / Power Rating: 1591 cc / -
Maximum Power Output: 93.8 kW (125 bhp)
Propellant: Petrol
Max Unladen Weight: 1345 kg
Maximum Laden Weight: 1800 kg
Open Market Value: \$14,528.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Feb 2029
Minimum PARF Benefit: \$7,264.00
No. of Transfers: 0
IU Label No.: 1129149571
COE No.: 2019030101000578Z
COE Expiry Date: 24 Feb 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
Quota Premium (QP) / Prevailing Quota Premium: \$25,689.00 / -
Actual QP Paid: \$25,689.00
QP (Regn Cat): \$25,689.00
OPC Cash Rebate Eligibility: No
QP during COE Bidding Exercise: \$25,689.00
Additional Registration Fee Rate: First \$14,528.00 (100%)
Actual ARF Paid: \$14,528.00
Vehicle Lifespan Expiry Date: No Lifespan
CO2 Emission: 152.00 (g/km)
CEV/VES Rebate Utilised Amount: -
CO Emission: 0.268410 (g/km)
HC Emission: 0.023310 (g/km)
NOx Emission: 0.008170 (g/km)
PM Emission: 0.300000 (mg/km)