



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21007446/Kqcn2 Date: 26/07/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 8637D	Veh. Inspected	SKF 645C	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10010798/CD	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	08/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JTDKD3B3701003297	Colour	METALLIC BLUE	
Odometer	215986 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	WINDFORCE	8 mm	
L/H Front Tyre	185/60 R15	WINDFORCE	8 mm	
R/H Rear Tyre	185/60 R15	ROADSTONE	6 mm	
L/H Rear Tyre	185/60 R15	ROADSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/07/2021	Inspection Date	09/07/2021	
Survey held at	BLK 1 SIN MING INDUSTRIAL SECTOR C #01-135			
Repairer	A T AUTO CONSULTANT			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	