

ASS. REC. BY:

REF:

AG2/21007446/1kg

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WVS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. C10010798/CD

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKF 645C

Yr Regn:

04, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pirus

C.C.

1497

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

215986

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTOK03B3701003287

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/60R15

R: Roadstone

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

6

mm

D.O.A.

8/7/21

D.O.I.

9/7/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Kenneth confirmed LS \$2750 (Red \$5339, 66%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 22/07 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Fields

Others

TOTAL

Report Format:

TP

Lump Sum \$2750

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

# A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113  
HP: 8386 8989 EMAIL:atautoconsultant@gmail.com  
Co. Reg. No.: 53368526E

Date of Estimate: 07.07.2021

Vehicle No: SKF645C

Owner: SG CAR FOR RENT PTE LTD

Date of Accident: 06.07.2021

Make & Model: TOYOTA PRIUS CVT

Chassis No : JTDKD3B3701003297

ESTIMATE FOR ACCIDENT VEHICLE NOS SKF645C

## PARTS

- |    |   |  |                     |
|----|---|--|---------------------|
| 1  | 1 | Tailgate                               |                     |
| 2  | 1 | Tailgate lock                          |                     |
| 3  | 1 | Tailgate weatherstrip                  |                     |
| 4  | 1 | Tailgate emblem "TOYOTA"               |                     |
| 5  | 1 | Tailgate emblem "PRIUS C"              |                     |
| 6  | 1 | Tailgate emblem "HYBRID SYNERGY DRIVE" |                     |
| 7  | 1 | Rear bumper                            |                     |
| 8  | 2 | Rear bumper side retainers RH/LH       | @ \$68.00           |
| 9  | 1 | Rear bumper reinforcement bar          |                     |
| 10 | 2 | Tail lamp RH/LH                        | M/S 0157 @ \$453.00 |
| 11 | 1 | Rear end panel top garnish             |                     |
| 12 | 1 | Rear exhaust system                    |                     |

SUB TOTAL

LESS 25%

DISCOUNTED SUB TOTAL

R \$1,283.00 ✓  
 R \$412.00 X  
 R \$332.00 X  
 R \$88.00 ✓  
 R \$76.00 ✓  
 R \$76.00 ✓  
 R \$560.00 ✓  
 @ \$136.00 ?  
 @ \$512.00 ?  
 @ \$906.00 ?  
 @ \$211.00 ?  
 R \$980.00 X

\$5,572.00

\$1,393.00

\$4,179.00

## S. NETT ITEM

- |   |      |                             |
|---|------|-----------------------------|
| 1 | 1set | Rear bumper reverse sensor  |
| 2 | 1set | Reverse camera              |
| 3 | 1    | Tailgate windscreen sealant |
| 4 | 1set | Rear number plate & garnish |

SUB TOTAL

LESS 0%

DISCOUNTED SUB TOTAL

R 280.00 ✓  
 R 450.00 X  
 R 120.00 ✓  
 R 60.00 ✓  
 \$910.00  
 \$0.00  
 \$910.00

## LABOUR

- |   |   |
|---|---|
| 1 | Panel beating for replace and repair affected parts |
| 2 | Spray painting on accident areas                    |
| 3 | Wiring charges                                      |
| 4 | Remove/refix reverse sensor                         |
| 5 | Remove/refix reverse camera                         |
| 6 | Remove/refix rear exhaust                           |
| 7 | Transfer tailgate windscreen                        |
| 8 | Transfer tailgate component                         |
| 9 | Apply undercoating to above affected areas          |

\$1,000.00 ?

\$1,000.00 600

\$80.00 150

\$120.00 50

R \$120.00 X

R \$120.00 X

\$200.00 120

\$180.00 60

\$180.00 ?

\$3,000.00

LKK Auto Consultants hence notify  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by Repairer

Signature:

Date:



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 06/07/2021 18:01 (SGT)  
Date of Accident ..... 06/07/2021 14:30 (SGT)  
Exact Location of Accident ..... PIE, Singapore  
Additional Location Information ..... ALONG PIE TOWARDS CHANGI  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SKF645C

#### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... SG CAR FOR RENT PTE. LTD.  
Company Reg No ..... 2XXXXX344N  
Email Address ..... SGCARFORRENTPTLTD@GMAIL.COM  
Mobile Phone No ..... (Phone) +65-96736134  
Alternative Phone No ..... (Home) +65-96736134

#### VEHICLE PARTICULARS

Manufacturer ..... Toyota  
Model ..... Prius  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private hire  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private hire  
Transmission ..... Auto  
CC ..... 0

#### INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... ThirdParty  
Fleet Policy ..... No  
Policy Number ..... 5112248624-01  
Cover Note Number ..... -

#### DRIVER

Name of Driver ..... GOH SOON WAH  
NRIC No ..... SXXXX358H



A-SKF645C  
B-SLQ8637D  
Date 06/07/2021  
Time 1430


P12 towards Charge

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On mentioned date and time, I was driving along P12 towards Charge on lane 1. As the car in front braked, I followed to slowed down. Suddenly I felt an impact from the rear. It was vehicle B that collided onto my rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:



  
Driver's Signature  
(if driver is not the policyholder)

  
Reporting Centre Personnel's Signature  
Name: