

Your Ref: 18/19/19/VP02/284628

Date: 28th July 2021

Our Ref: CS1/LPM21007472/Gtf3e2

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank

No. 6 Jalan Sultan Sulaiman

50000 Kuala Lumpur, Malaysia

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJG 2594J

INSURED VEHICLE: JMH 5538

ACCIDENT DATE: 06/05/2019

We thank you for your instruction on 08/07/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJG 2594J from M/s ST Appraisal Services..
- b) Final Repair Bill of SJG 2594J from M/s Teamwork Garage Pte Ltd.
- c) Singapore Accident Statement and Police Report of Vehicles SJG 2594J.
- d) Colour damaged vehicle photographs of SJG 2594J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJG 2594J
Make & Model	: Toyota Vios E Auto
Year of Registration	: 2008
Chassis Number	: MR053HY9305068074
Engine Capacity	: 1497 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.