

Our Job Ref No : 305477454 ComfortDelGro Engineering Pte Ltd Date 14/07/21 59 Loyang Drive Singapore 508969 Fax: 6546 8156 **FINALIZATION FORM** LKK Fax: **TAUFIKH** Attn : Mr SH 8875Y 08/07/21 Vehicle Reg No. Date of Accident: The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-TOKIO YL 4968Y The repair job shall bill to: The finalized amount shall be: 2. Spare Parts after List discount (a) \$1,807.16 (b) Labour Charges \$1,346.00 **Total for Part-By-Part Repair Cost** \$3,153.16 (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% Final Lumpsum Repair cost 3. Estimated normal period for repairs: 3 working days. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature: Signature: Taufikh Name JUMANI Name 22/7/21 : 62148315 Tel Date : 65468156 Fax For Official Use Only Document Confirm By Item Amount Attached Remarks (Signature) Yes or No 1. Rental Rate P/Day YES 2. Loss of Income Paid NO 3. Survey Fees LTA Search Fee \$7.49 / \$2.00 5. Medical Fees (on behalf of driver, if applicable) Overrun Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.07.2021

REPAIR ESTIMATE

Time: 16:53:19

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

JOB NO
SH 8875Y

MILEAGE
00000000000

COMPORT TRANSPORTATION FIE LIT

383 SIN MING DRIVE MAKE : HYUNDAI SINGAPORE SINGAPORE 575717 MODEL : IONIQ(G3) DATE OF REGN : 14.11.2019

DATE OF REGN : 14.11.2019
DATE/TIME IN : 08.07.2021 14:10

ACCIDENT DATE : 08.07.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0592-G PANEL ASSY-FRONT DOOR RH# 1 1,797.20 20.00 1,437.76

0002 04-01-0104-2574-G COVER-FR DR O/S HDL RH 1 33.20 20.00 26.56

0003 04-01-0104-2572-G GRIP-FRONT DOOR OUTSIDE R 1 234.80 20.00 187.84

0004 28-01-0103-0003-A FRT DOOR LOGO SONATA CTPL 1 N 75.00 2.00- 75.00

0005 28-01-9999-2023-A APP LOGO REAR DOOR L/R CT 1 N 80.00 0.20 80.00

SUB-TOTAL : 1,807.16

JOB NATURE

0000 PB PANEL BEATING 525.00

0001 SP SPRAYPAINT CHARGE 750.00

0002 L TRANSFER DOOR PART 60.00

0003 L MERIMEN FEE 11.00

SUB-TOTAL : 1,346.00

COMFORTDELGRO ENGINEERING PTE LTD

SURVEYOR NAME & SIGNATURE

Date: 13.07.2021 Time: 16:53:19

REPAIR ESTIMATE

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

305477454

REGN NO MILEAGE : SH 8875Y

MAKE

: 0000000000 : HYUNDAI

MODEL

: IONIQ(G3)

DATE OF REGN : 14.11.2019 DATE/TIME IN : 08.07.2021 14:1

ACCIDENT DATE : 08.07.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,153.16

AUTHORISED: YES/NO

MVA NAME & SIGNATURE

DATE:

DATE: