



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BERKLEY INSURANCE COMPANY (SINGAPORE BRANCH) Ref: CS/CWF21007494/Rtf3e2
C/O : CRAWFORD & COMPANY NO.8 SHENTON Date: 26/05/2022
WAY #03-01 AXA TOWER SINGAPORE 068811 Code: BIC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	BICYCLE	Veh. Inspected	SLQ 2554Z
Policy No.	1094714/G/EA	Coverage (\$)	0.00
Claim No.	BDH.C446.0012	Excess (\$)	0.00
Assign From	EUGENE ANG	Assign Date	09/07/2021

2. Vehicle Particulars & Condition

Make & Model	JAGUAR XJ 2.0 TSS SWB SR	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SAJAC12M8GPW01869	Colour	BLACK
Odometer	49218 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/40Z R19	PIRELLI	6 mm
L/H Front Tyre	275/40Z R19	PIRELLI	6 mm
R/H Rear Tyre	275/40Z R19	PIRELLI	6 mm
L/H Rear Tyre	275/40Z R19	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/06/2021	Inspection Date	23/07/2021
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**