



ALG- OD CLAIM
SURVEY: 09/07/21
LKK - STEVE

VEHICLE NO : SGC 5802 X

MODEL : KIA/CERATO 1.6 A GT LINE

WIP : 35809

Material	:	\$	<u>3,757.60</u>
Labour	:	\$	<u>3,120.00</u>
Sub-Total	:	\$	<u>6,877.60</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>6,577.60</u>
GST 7%	:	\$	<u>460.43</u>
Grand Total	:	\$	<u>7,038.03</u>

Re-Finalise By/Date : WIP ON 22/07/21

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 07 WORKING DAYS + 2 days (wk. end)

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /JACKSON LIM JEK SHENG (LIN YICH Reg No/Reg Date SGC5802X / 06/01/2020 Date In/Mileage 09/07/2021/ 34837 Chassis/Package KNAF5416MK5052314 /KC17P Engine No G4FGKH749375 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK
09/07/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/07/2021/ 08:35	BLC	884 / Lauro Songcuan	35809

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER, FRONT SUPPORT PANEL, REPAIR FRONT FENDER RH & LH, BONNET				1200.00 ✓
E PNT98000 SPRAY PAINT FOR FRONT BUMPER, BONNET, FRONT FENDER RH & LH				1400.00 ✓
E PNT88000 REMOVE & INSTALL AIRCON CONDENSER & RADIATOR				100.00 ✓
A 90000001 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80.00 ✓
M SUNDRY APPLY SEALANT FOR AFFECTED PORTIONS				40.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY ONE PC OF FRONT LICENSE PLATE WITH PLASTIC FRAME MODEL: CERATO				50.00 ?
S SPECIALISTJOB VACUUM AND TOP UP AIRCON GAS (CERATO)				80.00 ✓
X EXC EXCESS FOR OWN DAMAGE CLAIM				-300.00
X COVER-FR BUMPER ✓	1.00	633.00	20.00	506.40 ✓
X GRILLE ASSY-RADIATOR ✓	1.00	328.00	20.00	262.40 ✓
X GARNISH-RADIATOR GRILLE ✓	1.00	38.00	20.00	30.40 ✓
X ABSORBER-FRONT BUMPER ENERGY ✓	1.00	84.00	20.00	67.20 ✓
X CARRIER ASSY-FRONT END MODULE ✓	1.00	675.00	20.00	540.00 ✓
X ORNAMENT-KIA NO.115 ✓	1.00	32.00	20.00	25.60 ✓
X LAMP ASSY-HEAD,LH ✓	1.00	2210.00	20.00	1768.00 ✓
X CONDENSER ASSY-COOLER ?	1.00	687.00	20.00	549.60 ?

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

THIS IS NOT AN OFFICIAL TAX INVOICE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /JACKSON LIM JEK SHENG (LIN YICH Reg No/Reg Date SGC5802X / 06/01/2020 Date In/Mileage 09/07/2021/ 34837 Chassis/Package KNAF5416MK5052314 /KC17P Engine No G4FGKH749375 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK
09/07/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/07/2021/ 08:35	BLC	884 / Lauro Songcuan	35809

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X CLIP → <i>Supp.</i> Z TEXT OD CLAIM - AIG DOA: 08/07/2021 SURVEY: STEVE (LKK) 09/07/2021 07 DAYS	10.00	1.00	20.00	8.00
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	3,757.60	Nett	6,577.60
Labour	2,930.00	7% GST on	460.43
Standard Menu	0.00		
Specialist Job	130.00	Total Payable	7,038.03
Diagnostics Job	0.00		
Sundry/Others	-240.00		
Total(w/o GST)	6,577.60		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SGC 5802 X

<u>Materials</u>		<u>Cost \$</u>
1	Clip (10 pcs)	10.00 / nec
	20% Discount	2.00
		8.00
	7% GST	0.56
	Total	8.56

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SGC 5802XWIP: 35809

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Condenser Assy - Cooler	? / SUPP	Steve 15/7/21	✓ III - 1/4	93606 115000 ✓ 1426608 28003 ✓ 13/7/21
2	Clips 10 pcs	? / SUPP			
3	top up Air con gas	? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	13/7/21	Steve
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CelerioSURVEYOR: SGC 5802X



HOME

Online



CERATO/FORTE../2019/G 1.6 MPI..

VCI




Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0249

VCI Ver.

02.59

ECU Ver.

M-E-K-01-00-0190

OS Ver.

Android 10



HOME

Online



CERATO/FORTE../2019/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



ICU



CLU



WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0249

VCI Ver.

02.59

ECU Ver.

M-E-K-01-00-0190

OS Ver.

Android 10



HOME

Online



CERATO/FORTE../2019/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



ICU



CLU



WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0249

VCI Ver.

02.59

ECU Ver.

M-E-K-01-00-0190

OS Ver.

Android 10