



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                                                                                |                                                                                |      |                                                            |            |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|------|------------------------------------------------------------|------------|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                                                                                                                                   |                                                                                |      | Ref: CS3/CTI21007522/T1vc<br>Date: 12/07/2021<br>Code: CTI |            |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>                                                                                                                                                                                              |                                                                                |      |                                                            |            |
| Insured Veh.                                                                                                                                                                                                                                     | GBA 8993C                                                                      |      | Veh. Inspected                                             | CB 5330T   |
| Policy No.                                                                                                                                                                                                                                       |                                                                                |      | Coverage (\$)                                              | 0.00       |
| Claim No.                                                                                                                                                                                                                                        | SNM21D203800/C02/GBA8993<br>C/LEEPG                                            |      | Excess (\$)                                                | 0.00       |
| Assign From                                                                                                                                                                                                                                      | CECILIA LEE PENG GEOK                                                          |      | Assign Date                                                | 12/07/2021 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                                                                                    |                                                                                |      |                                                            |            |
| Make & Model                                                                                                                                                                                                                                     |                                                                                |      | c.c                                                        | 0          |
| Engine No.                                                                                                                                                                                                                                       | HIDDEN                                                                         |      | Year of Reg.                                               |            |
| Chassis No.                                                                                                                                                                                                                                      |                                                                                |      | Colour                                                     |            |
| Odometer                                                                                                                                                                                                                                         | -                                                                              |      | Steering                                                   |            |
| Brakes                                                                                                                                                                                                                                           |                                                                                |      | Modification                                               |            |
| General                                                                                                                                                                                                                                          |                                                                                |      |                                                            |            |
| <b>3. Conditions of Tyres</b>                                                                                                                                                                                                                    |                                                                                |      |                                                            |            |
|                                                                                                                                                                                                                                                  | Size                                                                           | Make | Balance                                                    |            |
| R/H Front Tyre                                                                                                                                                                                                                                   |                                                                                |      | mm                                                         |            |
| L/H Front Tyre                                                                                                                                                                                                                                   |                                                                                |      | mm                                                         |            |
| R/H Rear Tyre                                                                                                                                                                                                                                    |                                                                                |      | mm                                                         |            |
| L/H Rear Tyre                                                                                                                                                                                                                                    |                                                                                |      | mm                                                         |            |
| <b>4. Description of Damages</b>                                                                                                                                                                                                                 |                                                                                |      |                                                            |            |
|                                                                                                                                                                                                                                                  |                                                                                |      |                                                            |            |
| <b>5. General Information</b>                                                                                                                                                                                                                    |                                                                                |      |                                                            |            |
| Accident Date                                                                                                                                                                                                                                    | 05/07/2021                                                                     |      | Inspection Date                                            | 21/07/2021 |
| Survey held at                                                                                                                                                                                                                                   | PRECISE AUTO SERVICE<br>NO.1 KAKI BUKIT AVE 6<br>#02-34/36<br>SINGAPORE 417883 |      |                                                            |            |
| <b>5a. Remarks</b>                                                                                                                                                                                                                               |                                                                                |      |                                                            |            |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |                                                                                |      |                                                            |            |