

Our Job Ref No : 305477774

Date 13/07/21

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. SHC1862L

Date of Accident : 09/07/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: SMRT (BUS) --- SMB1493P
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$435.12
(b) Labour Charges	\$630.00
Total for Part-By-Part Repair Cost	\$1,065.12
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
 Name : JUMANI
 Tel : 62148315
 Fax : 65468156

Signature : taufikh
 Name : Taufikh
 Date : 26/7/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305477774
 REGN NO : SHC1862L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 14.11.2019
 DATE/TIME IN : 12.07.2021 10:35
 ACCIDENT DATE : 09.07.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0003	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00

SUB-TOTAL : 435.12

JOB NATURE

0000	PB	PANEL BEATING				350.00
0001	SP	SPRAYPAINT CHARGE				250.00
0002	L	REMOVE/REFIX REVERSE SENSOR				30.00

SUB-TOTAL : 630.00

TOTAL : 1,065.12

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :