

SMART (PIP) JU

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 12.07.2021  
Time: 11:03:54  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305477774  
REGN NO : SHC1862L  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 14.11.2019  
DATE/TIME IN : 12.07.2021 10:35  
ACCIDENT DATE : 09.07.2021

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	de ✓
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	un ✓
0003	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	un ✓

SUB-TOTAL : 435.12 ✓

JOB NATURE

0000	PB	PANEL BEATING		400.00		350.
0001	SP	SPRAYPAINT CHARGE		300.00		250
0002	L	REMOVE/REFIX REVERSE SENSOR		80.00		30 630.

SUB-TOTAL : 780.00

TOTAL : 1,215.12

Jumani  
MVA NAME & SIGNATURE  
DATE: 12/7/21

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE:

435.12  
630  
\$ 1065.12  
02 days #

Tanpin 97493749  
wp' 12/7/21 e qm  
02 days  
MP Remuy before paint  
furniture khantown

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: