

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	▼	📄	✓	🖨	Find   Next
---	---	---	--------	---	---	---	---	------	---	---	---	---	-------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SMRT AUTOMOTIVE SERVICES PTE LTD		Ref: CS/SMR21007530/T1u3	
60 WOODLANDS INDUSTRIAL PARK		Date: 12/07/2021	
E4SINGAPORE 757705		Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SMB 1493P	<b>Veh. Inspected</b>	SHC 1862L
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	BUS/07/21/5032/PT	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HUA YEN	<b>Assign Date</b>	12/07/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
<b>Accident Date</b>	09/07/2021	<b>Inspection Date</b>	<del>12/07/2021</del> 13/07/2021
<b>Survey held at</b>	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			