

ASS. REC. BY:

REF: ~~CS3/ASM21001329/G~~

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

12.07.2021

From (Person): CHAN KIAN CHUAN of AXA Date/Time: ~~28/1/2021 11:10 AM~~

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCX 888T Insured: SHC 8138Z

at Workshop m/s Teamwork Garage Pte Ltd Tel: 6844 2475

of Blk 53 Ubi Avenue 1#01-24 Paya Ubi

Policy No: Claim No: S1M031J9

Sum Insured: Excess:

Make of Veh: D.O.A. 15.01.2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 28-01-21 11.31A.M Person Contacted: DARREN Vehicle IN ☒ OUT

Date/Time	Action/Instruction (X) Estimate
	SCX 888T- X
	SHC 8138Z - CC3/CTI20013814/R1ra3 DOA :14/12/2020
3/2/21	Send IA via Smart Claim
3/2/21	Submit PRS, repair range \$4,000-\$5,000 (4 days)