


NOT Authorized
Lim Tan Motor
Meaning After Paint
5 days



ESTIMATE TO REPAIR

VEHICLE NO. : SKZ 6020 K
 MAKE : NISSAN
 MODEL : SYLPHY 1.6 CVT
 YEAR : 2015
 CHASSIS NO : MNTBBAB17Z0026704

SURVEYOR NAME : *Kenneth*
 DATE OF SURVEY : *13.07.21*
 TIME OF SURVEY :

DATE : 12.07.2021
 DATE OF ACCIDENT : 10.07.2021
 THIRD PARTY REF : GBF 2956 Z/AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1PC	REAR BUMPER <i>807</i>			<i>Net</i>	\$686.20 NETT
1PC	REAR BUMPER SPONGE CENTRE			<i>Net</i>	\$49.60 NETT
2PCS	REAR BUMPER SPONGE SIDE		\$ 145.30	<i>Net</i>	\$290.60 NETT
2PCS	REAR BUMPER SENSOR		\$ 298.40	<i>Net</i>	\$596.80 NETT
2PCS	REAR BUMPER RETAINER		\$ 51.20	<i>Net</i>	\$102.40 NETT
10PCS	REAR BUMPER CLIPS		\$ 2.60	<i>Net</i>	\$26.00 NETT
1PC	REAR END PANEL			<i>Net</i>	\$454.30 NETT
1PC	REAR END PANEL GARNISH			<i>Net</i>	\$185.00 NETT
1PC	REAR BOOT LID <i>980.15</i>			<i>Net</i>	\$1244.80 NETT
1PC	REAR BOOT RUBBER			<i>Net</i>	\$99.80 NETT
1PC	REAR BOOT LOCK			<i>Net</i>	\$135.70 NETT
2PCS	REAR BOOT LAMPS		\$ 163.30	<i>Net</i>	\$326.60 NETT
1PC	REAR BOOT OUTER CHROME			<i>Net</i>	\$189.90 NETT
1PC	REAR BOOT LOWER CHROME			<i>Net</i>	\$155.10 NETT
1PC	REAR BOOT EMBLEM			<i>Net</i>	\$79.90 NETT
1PC	REAR BOOT SYLPHY EMBLEM			<i>Net</i>	\$94.70 NETT
1PC	O/S REAR BOOT EMBLEM			<i>Net</i>	\$59.70 NETT
2PCS	TAIL LAMPS		\$397.80	<i>Net</i>	\$795.60 NETT
	LESS 10%				\$ 5,572.70
					\$ 557.27
					\$ 5,015.43
	REAR NUMBER PLATE	S/N		<i>Net</i>	\$ 40.00
	TO PUTTY & SPRAY PAINT				\$ 800.00
	TO ANTI RUST				\$ 80.00
	TO CHECK REAR WIRING & WATER LEAKAGE				\$ 30.00
	LABOUR CHARGES				\$ 700.00
TG/TL	TOTAL				\$ 6,665.43

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____