

ASS. REC. BY:

Steve

REF

CS/001 21907543 IE+13

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

M12D16122107

Sum Insured:

Excess:


750.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Rel. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFN 8833R

Yr Regn:

28/9/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X3

c.c

1998

Colour:

white

A/C:

Insured / Std / NI / N

Sp. Reading

39555

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

WRA TR 120 FOLC 94425

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brakes: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/50R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

9/7/21

D.O.A.

13/7/21

Survey held at

Performance Motors

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

NIV - 165 K

Confirm part by part \$38,708.60, 15 days

RED: 8757.25; 18%

File/Time, File, Pass W/L



: Prel. Report



: Final Report

File/Time, File Return to?

Days Of Repair:

15

Resurvey No. of Trips:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$1

Phone

Others

TOTAL

49725=1225

250+1225

60

80+80

266

580

1961

19/10/21