SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/07/2021 17:28 (SGT) Date of Accident 09/07/2021 15:05 (SGT) Exact Location of Accident Pasir Ris Drive 3, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLF8006J

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner LEE CHEOW HUAT BERNARD NRIC No. SXXXX167E Email Address ISHAREAUTO@GMAIL.COM Mobile Phone No (Phone) +65-94599735 Alternative Phone No (Home) +65-94599735

VEHICLE PARTICULARS

Manufacturer Toyota Model Noah Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto

INSURANCE COMPANY

Name of Insurance Company FWD Singapore Pte. Ltd. Type of Coverage Comprehensive Fleet Policy Policy Number PNPV2020-00004090-01 Cover Note Number

DRIVER

Name of Driver LEE CHEOW HUAT BERNARD SXXXX167E

Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	05/01/1970 Indoor 26/06/1991 30 YEARS AND 1 MONTH Male (Phone) +65-94599735 (Home) +65-94599735 ISHAREAUTO@GMAIL.COM APT BLK 147 PASIR RIS GROVE #01-70 - 518138 Yes - No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Collision - Head to Rear Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No 2 Yes No Yes 3
PASSENGER 1	
Name Gender	KIM MYUNG SUN Female
PASSENGER 2 Name Gender	LEE JI SUN JASMINE Female
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?	No No
CIRCUMSTANCES OF ACCIDENT	
REFER TO ATTACHED	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes No No
DETAILS OF OTHER	VEHICLE PROPERTY 1

SHC661G

Accident report SY0A217C000B

Vehicle Registration Number
Vehicle Manufacturer

Vehicle Model	_
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	LEE CHEOW HUAT BERNARD
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SLF8006J
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (if driver is not the policyholder) / Date

Witnessee by Reporting Centre Personnel

Sketch Plan

ed > PX

& Time

A= 5LF 8006 H B= 5HC 661 G

T- Junction Of Pasir Ris Drive 3

and Pasir Ris Street 52

cribe Circumstances of the Accident	
	/
Refer to Attached	X
/	

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

On 09.07.2021 at about 15:05 hours at T-Junction of Pasir Ris Drive 3 and Pasir Ris Street 52, I was stationary on lane 2 (along Pasir Ris Drive 3 towards Pasir Ris West) and waiting for the traffic light to turn green.

Suddenly, I heard a loud bang and felt an impact. When I alighted, I realised it was vehicle (B) that collided onto the rear portion of my vehicle (A).

I wish to state that I have 2 passengers in my vehicle (A).

Vehicle (A): SLF 8006H

Vehicle (B): SHC 661G