

Our Ref: CT21070125

Date: 27 July 2021



**TO WHOM IT MAY CONCERN**

Dear Sir/Madam

ACCIDENT ON                      10/07/2021    @   13:40 hrs  
ALONG                                HOUGANG ST 21 BLK 221  
INVOLVING                         SKK5305A

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC1465A** (the "Taxi"). The Taxi was hired to **SIM CHEE KIONG IC NO SXXXX472C** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$126.47** per day (inclusive of GST).

Please be advised that the Taxi was insured with **AXA Insurance Singapore Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Philip Chia  
Manager, Fleet Safety

This is a computer generated letter. No signature is required.

DATE \_\_\_\_\_

1124

DATE \_\_\_\_\_

1124

MILEAGE  
TRAVELLED  
(KM)

1124

HOURS OPERATED (TIME)

FROM \_\_\_\_\_ TO \_\_\_\_\_

(KM)

HOURS OPERATED (TIME)

FROM \_\_\_\_\_ TO \_\_\_\_\_

(KM)

DATE \_\_\_\_\_

NAME OF DRIVER

11-7-2021

Soon,

1	8	9	4	0	4
---	---	---	---	---	---

致

11:30	11:30
-------	-------

10.11.11

Acron

7

27

545

14-7-2

1000000

A hand-drawn diagram of a cell on a grid background. The cell is represented by a large, irregular oval shape. Inside the cell, there is a smaller, roughly circular nucleus. To the right of the nucleus, there is a large, clear, oval-shaped vacuole. The cell is drawn with simple black outlines.

121

9