

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS3/SMO20011303/R1Ktf3e2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	Date:	11/08/2021	
			Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJZ 3317L	Veh. Inspected	SGL 6673Y	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD2003036/GPL	Excess (\$)	0.00	
	Assign From	GNOH PAU LOONG	Assign Date	13/07/2021	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA WISH 1.8A	c.c	1794	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	ZNE100320680	Colour	GREY	
	Odometer	221514 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	15/10/2020	Inspection Date	19/10/2020	
	Survey held at	SINCERELEAD GARAGE PTE L	TD		
		2 BUROH CRESCENT, #02-09 ACE @ BUROH SINGAPORE 627546			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
_					