

12/12/2020

REF: CS3/SMO20011303/R1Ktf3-1 Special Instruction:

ASS. REC. BY:

SURVEYOR: RASUL

ASSIGNMENT (Office)

From (Person): GNOH PAO LOONG of SMO

Date/Time: 13/7/2021 9:31 AM

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGL 6673Y

Insured: SJZ 3317L

at Workshop m/s SINCERE LEAD GARAGE

Tel: +65 9815 8858

of 2 Buroh Crescent #02-09 Ace@Buroh

Policy No:

Claim No: CMTD2003036/GPL

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 15/10/2020

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 3.07PM@19/10/2020

Person Contacted:

MS.XIAO

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SGL 6673Y-X
	SJZ 3317L-CC3/AIG16006541/Khg3q2 DOA :07/04/2016